



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202602-32657

If you have any questions, please state the report number and date

Date: 18.02.2026

Report

Subject	Report
Inspection date/location	16.02.2026 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	HK-BV 600E
Vehicle Identification Number	W1N1673171A608362

REPORTNUMBER: 202602-32657

If you have any questions, please state the report number and date

Date: 18.02.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	16.02.2026 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	HK-BV 600E
Vehicle type	Estate Car
Manufacturer	Mercedes-Benz
Model / Sales description	GLE 350
Key numbers HSN/TSN	2222 / ASN
Vehicle identification number	W1N1673171A608362
Previous owners	1
First registration	16.12.2021
Mileage	120.362 km
Colour / Colour Code	
Fuel Type	Hybrid/Diesel
Cubic Capacity / Power	1.950 cm ³ / 143 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	10.07.2025 / 106.229 km
Next vehicle inspection	30.07.2027
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202602-32657

If you have any questions, please state the report number and date

Date: 18.02.2026

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 275/55 R19 front axle	Summer tyre on Aluminium rim	6/6
#2 275/55 R19 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Windshield	Stone chip	Slight	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Door r.l.; ~ 200µm
- Fender ri.; ~ 180µm
- Side panel ri.; ~ 200µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

REPORTNUMBER: 202602-32657

If you have any questions, please state the report number and date

Date: 18.02.2026

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 18.02.2026



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 13 overview pictures, 3 damage pictures

REPORTNUMBER: 202602-32657

If you have any questions, please state the report number and date

Date: 18.02.2026

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202602-32657

If you have any questions, please state the report number and date

Date: 18.02.2026



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202602-32657

If you have any questions, please state the report number and date

Date: 18.02.2026



Image 13

Damage pictures



Image 1:



Image 2:



Image 3: