

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202409-27677 If you have any questions, please state the report number and date

Date: 20.09.2024

Report

Subject Inspection date/location

Client Registration number Vehicle Identification Number Report 20.09.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra

VXKUBYHTKM4380421



Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202409-27677 If you have any questions, please state the report number and date

Date: 20.09.2024

Report

Subject Client Inspection date/location

Registration number Vehicle type Manufacturer Model / Sales description Key numbers HSN/TSN Vehicle identification number **Previous owners First registration** Mileage **Colour / Colour Code** Fuel Type **Cubic Capacity / Power** Number of doors / seats Transmission Number of kevs Last maintenance Next vehicle inspection Service documentation **Trailer coupling Rain sensor Operating manual** Repainting

Inspection Condition

Report Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra 20.09.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra

Saloon Opel Corsa Start/Stop Edition 1.5 1889 / ABW VXKUBYHTKM4380421 1 12.01.2022 155.187 km Weiß Diesel 1.499 cm³ / 75 kW 5/5Manual gearbox 1 11.07.2024 / 155.109 km 01.01.2025 Nonexistent No Unavailable Available Found Plastic parts could not be evaluated by means of paint thickness measurement. non-dismantled, roadworthy, traffic safe



If you have any questions, please state the report number and date

Date: 20.09.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 195/65 R16 front axle #2 195/65 R16 rear axle	Winter tyre on Steel rim with wheel cover	6/6 6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	good
Disc	adequate	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Slight	
2	Bonnet	Stone chip	Slight	
3	Tailgate	Scratch	Medium	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Bumper fr.;

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.



If you have any questions, please state the report number and date

Date: 20.09.2024

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 20.09.2024

Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 17 overview pictures, 3 damage pictures



If you have any questions, please state the report number and date

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

Date: 20.09.2024

Overview pictures



Image 1



Image 3



Image 5



Image 2



Image 4



Image 6



If you have any questions, please state the report number and date

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

Date: 20.09.2024













Image 11





Image 12



If you have any questions, please state the report number and date

Date: 20.09.2024







Image 15



Image 17



Image 14



Image 16



If you have any questions, please state the report number and date

Date: 20.09.2024

DE-36199 Rotenburg a.d. Fulda/Lisp.

Gerlach & Schröder GbR

Nürnberger Str. 34

Damage pictures



Image 1: Siehe Pos.1



Image 3: Siehe Pos.3



Image 2: Siehe Pos.2