



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202507-30735

If you have any questions, please state the report number and date

Date: 03.07.2025

Report

Subject	Report
Inspection date/location	02.07.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	
Vehicle Identification Number	LGXC74C45S0217595

REPORTNUMBER: 202507-30735

If you have any questions, please state the report number and date

Date: 03.07.2025

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	02.07.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	
Vehicle type	SUV/Off-road Vehicle/Pickup Truck
Manufacturer	BYD
Model / Sales description	SEAL U DMi
Key numbers HSN/TSN	/
Vehicle identification number	LGXC74C45S0217595
Previous owners	0
First registration	30.04.2025
Mileage	20 km
Colour / Colour Code	
Fuel Type	Electric
Cubic Capacity / Power	1.498 cm ³ / 160 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	Unknown
Next vehicle inspection	
Service documentation	Nonexistent
Trailer coupling	No
Rain sensor	Available
Operating manual	Unavailable
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202507-30735

If you have any questions, please state the report number and date

Date: 03.07.2025

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 235/50 R19 front axle	Summer tyre on Aluminium rim	8/8
#2 235/50 R19 rear axle		8/8

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	near-new	near-new
Disc	near-new	near-new

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
-----	-----------	--------	----------	---------

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Engine bonnet; ~ 250µm
- Roof; ~ 210µm
- Tailgate; ~ 210µm
- Fender le; ~ 190µm
- Door f.l.; ~ 190µm
- Door r.l.;
- Side panel le.; ~ 210µm
- Fender ri.; ~ 180µm
- Door f.r.; ~ 190µm
- Door r.r.; ~ 180µm
- Side panel ri.; ~ 210µm

REPORTNUMBER: 202507-30735

If you have any questions, please state the report number and date

Date: 03.07.2025

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 03.07.2025



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 18 overview pictures, 0 damage pictures

REPORTNUMBER: 202507-30735

If you have any questions, please state the report number and date

Date: 03.07.2025

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202507-30735

If you have any questions, please state the report number and date

Date: 03.07.2025



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202507-30735

If you have any questions, please state the report number and date

Date: 03.07.2025



Image 13



Image 14



Image 15



Image 16



Image 17



Image 18