



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202409-27590

If you have any questions, please state the report number and date

Date: 12.09.2024

Report

Subject	Report
Inspection date/location	12.09.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	M-LQ 704
Vehicle Identification Number	ZFA26300006N79172



REPORTNUMBER: 202409-27590

If you have any questions, please state the report number and date

Date: 12.09.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	12.09.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	M-LQ 704
Vehicle type	
Manufacturer	Fiat
Model / Sales description	Doblo Cargo
Key numbers HSN/TSN	1727 / AIQ
Vehicle identification number	ZFA26300006N79172
Previous owners	1
First registration	05.12.2019
Mileage	82.078 km
Colour / Colour Code	Weiss
Fuel Type	Diesel
Cubic Capacity / Power	1.248 cm ³ / 70 kW
Number of doors / seats	4 / 2
Transmission	Manual gearbox
Number of keys	1
Last maintenance	Unknown
Next vehicle inspection	01.04.2026
Service documentation	Nonexistent
Trailer coupling	No
Rain sensor	Unavailable
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202409-27590

If you have any questions, please state the report number and date

Date: 12.09.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 185/65 R15 front axle	Summer tyre on Aluminium rim	6/6
#2 185/65 R15 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Dent	Medium	
2	Bumper front	Scratch	Slight	
3	Fender ri	Dent	Medium	
4	Bumper rear	Scratch	Slight	
5	Door FL	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202409-27590

If you have any questions, please state the report number and date

Date: 12.09.2024

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 12.09.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 11 overview pictures, 5 damage pictures

REPORTNUMBER: 202409-27590

If you have any questions, please state the report number and date

Date: 12.09.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202409-27590

If you have any questions, please state the report number and date

Date: 12.09.2024



Image 7



Image 8



Image 9



Image 10



Image 11

REPORTNUMBER: 202409-27590

If you have any questions, please state the report number and date

Date: 12.09.2024

Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2



Image 3: siehe pos.3



Image 4: siehe pos.4



Image 5: siehe pos.5