



Gerlach & Schröder GbR  
Nürnberger Str. 34  
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25925

If you have any questions, please state the report number and date

Date: 22.04.2024

## Report

<b>Subject</b>	Report
<b>Inspection date/location</b>	15.04.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Registration number</b>	BT-KS 3003
<b>Vehicle Identification Number</b>	VXEVFEHZ8LZ002670



REPORTNUMBER: 202404-25925

If you have any questions, please state the report number and date

Date: 22.04.2024

## Report

<b>Subject</b>	Report
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Inspection date/location</b>	15.04.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Registration number</b>	BT-KS 3003
<b>Vehicle type</b>	Estate Car
<b>Manufacturer</b>	Opel
<b>Model / Sales description</b>	Vivaro 2.0 D CARGO M AUTM.
<b>Key numbers HSN/TSN</b>	3003 / AXZ
<b>Vehicle identification number</b>	VXEVFEHZ8LZ002670
<b>Previous owners</b>	2
<b>First registration</b>	16.09.2019
<b>Mileage</b>	121.801 km
<b>Colour / Colour Code</b>	GRAU
<b>Fuel Type</b>	Diesel
<b>Cubic Capacity / Power</b>	2.000 cm <sup>3</sup> / 130 kW
<b>Number of doors / seats</b>	4 / 3
<b>Transmission</b>	Automatic transmission
<b>Number of keys</b>	2
<b>Last maintenance</b>	14.09.2022 / 86.079 km
<b>Next vehicle inspection</b>	01.09.2023
<b>Service documentation</b>	Available
<b>Trailer coupling</b>	No
<b>Rain sensor</b>	Available
<b>Operating manual</b>	Available
<b>Repainting</b>	Found Plastic parts could not be evaluated by means of paint thickness measurement.
<b>Inspection Condition</b>	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202404-25925

If you have any questions, please state the report number and date

Date: 22.04.2024

### Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 215/60 R17 front axle	All-season tyre on Steel rim	7/7
#2 215/60 R17 rear axle		7/7

The state of the tyres is roadworthy.

### Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

### Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bumper front	Stone chip	Slight	
2	Door FR	Scratch	Slight	
3	Door RR	Scratch	Slight	
4	Bumper rear	Scratch	Slight	
5	Door FL	Scratch	Slight	

### Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Door r.r.; ~ 170µm
- Bumper re.;

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

REPORTNUMBER: 202404-25925

If you have any questions, please state the report number and date

Date: 22.04.2024

## Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

## Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 22.04.2024



---

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

**Attached:** 13 overview pictures, 5 damage pictures

REPORTNUMBER: 202404-25925

If you have any questions, please state the report number and date

Date: 22.04.2024

## Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-25925

If you have any questions, please state the report number and date

Date: 22.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-25925

If you have any questions, please state the report number and date

Date: 22.04.2024

Bestätigung		
Inspektion aktion 51462	Service: <input type="checkbox"/> Zwischeninspektion <input checked="" type="checkbox"/> Hauptinspektion	Service: <input type="checkbox"/> Zwischeninspektion <input type="checkbox"/> Hauptinspektion
	Datum: 14.9.22 km: 86079	Datum: km:
dexos2 <input checked="" type="checkbox"/>	Motoröl Klasse: dexos1 <input type="checkbox"/> dexos2 <input checked="" type="checkbox"/> dexos1 Gen2 <input type="checkbox"/> ACEA A3 <input type="checkbox"/> B4 <input type="checkbox"/> C3 <input type="checkbox"/>	Motoröl Klasse: dexos1 <input type="checkbox"/> dexos1 Gen2 <input type="checkbox"/> ACEA A3 <input type="checkbox"/> B4 <input type="checkbox"/>
B4 <input type="checkbox"/> C3 <input type="checkbox"/> 0 W-30	Viskosität: 0 W-30	Viskosität:
Gefrierschutz, Kühlfüssigkeit °C	Gefrierschutz, Kühlfüssigkeit °C	Gefrierschutz, Kühlfüssigkeit °C
Ja <input type="checkbox"/> Nein <input checked="" type="checkbox"/>	Ja <input type="checkbox"/> Nein <input checked="" type="checkbox"/>	Ja <input type="checkbox"/> Nein <input checked="" type="checkbox"/>
Batterie (Funkfernbedienung)	Batterie (Funkfernbedienung)	Batterie (Funkfernbedienung)
Innenraumluftfilter	Innenraumluftfilter	Innenraumluftfilter
Luftfiltereinsatz	Luftfiltereinsatz	Luftfiltereinsatz
Keilrippenriemen	Keilrippenriemen	Keilrippenriemen
Zahnriemen	Zahnriemen	Zahnriemen

Image 13

## Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2



Image 3: siehe pos.3



Image 4: siehe pos.4

REPORTNUMBER: 202404-25925

If you have any questions, please state the report number and date

Date: 22.04.2024



Image 5: siehe pos.5