



Gerlach & Schröder GbR  
Nürnberger Str. 34  
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-26028

If you have any questions, please state the report number and date

Date: 22.04.2024

## Report

<b>Subject</b>	Report
<b>Inspection date/location</b>	22.04.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Registration number</b>	KR-CD444
<b>Vehicle Identification Number</b>	TMBJG7NE1J0360750



REPORTNUMBER: 202404-26028

If you have any questions, please state the report number and date

Date: 22.04.2024

## Report

<b>Subject</b>	Report
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Inspection date/location</b>	22.04.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Registration number</b>	KR-CD444
<b>Vehicle type</b>	Estate Car
<b>Manufacturer</b>	Skoda
<b>Model / Sales description</b>	Octavia Com.1.6TDI Clever
<b>Key numbers HSN/TSN</b>	8004 / ASF
<b>Vehicle identification number</b>	TMBJG7NE1J0360750
<b>Previous owners</b>	1
<b>First registration</b>	17.07.2018
<b>Mileage</b>	167.163 km
<b>Colour / Colour Code</b>	schwarz
<b>Fuel Type</b>	Diesel
<b>Cubic Capacity / Power</b>	1.598 cm <sup>3</sup> / 85 kW
<b>Number of doors / seats</b>	5 / 5
<b>Transmission</b>	Manual gearbox
<b>Number of keys</b>	2
<b>Last maintenance</b>	13.10.2023 / 155.257 km
<b>Next vehicle inspection</b>	01.07.2025
<b>Service documentation</b>	Available
<b>Trailer coupling</b>	No
<b>Rain sensor</b>	Available
<b>Operating manual</b>	Available
<b>Repainting</b>	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
<b>Inspection Condition</b>	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202404-26028

If you have any questions, please state the report number and date

Date: 22.04.2024

### Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/45 R17 front axle	Summer tyre on Aluminium rim	6/6
#2 225/45 R17 rear axle		5/5

The state of the tyres is roadworthy.

### Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

### Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim RL	Scratch	Slight	
2	Aluminium rim RR	Scratch	Slight	
3	Bonnet	Stone chip	Slight	
4	Bumper front		Slight	
5	Windshield	Stone chip	Slight	
6	Door entry FL	Scratch	Slight	
7	Door RL		Medium	
8	Door entry RL	Scratch	Slight	
9	Side panel left	Dent	Slight	
10	Bumper rear	Scratch	Slight	
11	Side panel right	Dent	Slight	
12	Door RR	Stone chip	Slight	



REPORTNUMBER: 202404-26028

If you have any questions, please state the report number and date

Date: 22.04.2024

## Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



REPORTNUMBER: 202404-26028

If you have any questions, please state the report number and date

Date: 22.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-26028

If you have any questions, please state the report number and date

Date: 22.04.2024



Image 13



Image 14



Image 15



Image 16



Image 17



REPORTNUMBER: 202404-26028

If you have any questions, please state the report number and date

Date: 22.04.2024

## Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.7



Image 8: Siehe Pos.7



REPORTNUMBER: 202404-26028

If you have any questions, please state the report number and date

Date: 22.04.2024



Image 9: Siehe Pos.7



Image 10: Siehe Pos.8



Image 11: Siehe Pos.9



Image 12: Siehe Pos.10



Image 13: Siehe Pos.11



Image 14: Siehe Pos.12



Image 15: Siehe Pos.13