



Gerlach & Schröder GbR  
Nürnberger Str. 34  
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-26114

If you have any questions, please state the report number and date

Date: 29.04.2024

## Report

|                                      |   |
|--------------------------------------|---|
| <b>Subject</b>                       | Report  |
| <b>Inspection date/location</b>      | 29.04.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2,<br>DE-36179 Bebra |
| <b>Client</b>                        | Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra                |
| <b>Registration number</b>           | K-UM1098  |
| <b>Vehicle Identification Number</b> | WDF44760113369789   |



REPORTNUMBER: 202404-26114

If you have any questions, please state the report number and date

Date: 29.04.2024

## Report

|                                      |  |
|--------------------------------------|--|
| <b>Subject</b>                       | Report   |
| <b>Client</b>                        | Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra                                   |
| <b>Inspection date/location</b>      | 29.04.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra                       |
| <b>Registration number</b>           | K-UM1098   |
| <b>Vehicle type</b>                  | Minivan/Minibus  |
| <b>Manufacturer</b>                  | Mercedes-Benz  |
| <b>Model / Sales description</b>     | Vito 114 CDI Komp.   |
| <b>Key numbers HSN/TSN</b>           | 1313 / BRJ   |
| <b>Vehicle identification number</b> | WDF44760113369789  |
| <b>Previous owners</b>               | 2  |
| <b>First registration</b>            | 05.12.2017   |
| <b>Mileage</b>                       | 182.694 km   |
| <b>Colour / Colour Code</b>          |  |
| <b>Fuel Type</b>                     | Diesel   |
| <b>Cubic Capacity / Power</b>        | 2.143 cm <sup>3</sup> / 100 kW   |
| <b>Number of doors / seats</b>       | 4 / 2  |
| <b>Transmission</b>                  | Automatic transmission   |
| <b>Number of keys</b>                | 2  |
| <b>Last maintenance</b>              | 17.03.2022 / 130.364 km  |
| <b>Next vehicle inspection</b>       | 01.12.2025   |
| <b>Service documentation</b>         | Available  |
| <b>Trailer coupling</b>              | No   |
| <b>Rain sensor</b>                   | Unavailable  |
| <b>Operating manual</b>              | Available  |
| <b>Repainting</b>                    | Not Found<br>Plastic parts could not be evaluated by means of paint thickness measurement. |
| <b>Inspection Condition</b>          | non-dismantled, roadworthy, traffic safe   |

REPORTNUMBER: 202404-26114

If you have any questions, please state the report number and date

Date: 29.04.2024

### Tires / Rims

| Axis / Size              | Tires                    | Profile [mm] |
|--------------------------|--------------------------|--------------|
| #1 225/55 R17 front axle | Winter tyre on Steel rim | 6/6          |
| #2 225/55 R17 rear axle  |                          | 8/8          |

The state of the tyres is roadworthy.

### Brakes

|        | Front axle | Rear axle |
|--------|------------|-----------|
| Lining | adequate   | adequate  |
| Disc   | adequate   | adequate  |

### Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

| Nr. | Component       | Damage     | Severity | Comment |
|-----|-----------------|------------|----------|---------|
| 1   | Bonnet          | Stone chip | Slight   |         |
| 2   | Bumper front    | Stone chip | Slight   |         |
| 3   | Fender ri       | Scratch    | Slight   |         |
| 4   | Door FR         | Scratch    | Slight   |         |
| 5   | Door RR         | Scratch    | Slight   |         |
| 6   | Side panel left | Scratch    | Slight   |         |
| 7   | Door FL         | Scratch    | Slight   |         |

### Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202404-26114

If you have any questions, please state the report number and date

Date: 29.04.2024

## Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

## Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 29.04.2024



---

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

**Attached:** 12 overview pictures, 7 damage pictures

REPORTNUMBER: 202404-26114

If you have any questions, please state the report number and date

Date: 29.04.2024

## Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



REPORTNUMBER: 202404-26114

If you have any questions, please state the report number and date

Date: 29.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11




Image 12

REPORTNUMBER: 202404-26114

If you have any questions, please state the report number and date

Date: 29.04.2024

## Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2



Image 3: siehe pos.3




Image 4: siehe pos.4



Image 5: siehe pos.5




Image 6: siehe pos.6



Image 7: siehe pos.7