



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202409-27646

If you have any questions, please state the report number and date

Date: 18.09.2024

Report

Subject	Report
Inspection date/location	18.09.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	R-UH836E
Vehicle Identification Number	LSJA24394MN091989



REPORTNUMBER: 202409-27646

If you have any questions, please state the report number and date

Date: 18.09.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	18.09.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	R-UH836E
Vehicle type	Saloon
Manufacturer	MG
Model / Sales description	EHS PHEV Comfort
Key numbers HSN/TSN	2180 / AAB
Vehicle identification number	LSJA24394MN091989
Previous owners	1
First registration	28.10.2021
Mileage	24.516 km
Colour / Colour Code	weiß
Fuel Type	Hybrid
Cubic Capacity / Power	1.490 cm ³ / 119 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	06.09.2023 / 21.869 km
Next vehicle inspection	01.10.2024
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202409-27646

If you have any questions, please state the report number and date

Date: 18.09.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 235/50 R18 front axle	Summer tyre on Aluminium rim	7/7
#2 235/50 R18 rear axle		7/7

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	near-new	near-new
Disc	near-new	near-new

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Medium	
2	Bonnet	Stone chip	Slight	
3	Tailgate	Dent	Slight	
4	Door RR	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202409-27646

If you have any questions, please state the report number and date

Date: 18.09.2024

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 18.09.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 4 damage pictures

REPORTNUMBER: 202409-27646

If you have any questions, please state the report number and date

Date: 18.09.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202409-27646

If you have any questions, please state the report number and date

Date: 18.09.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202409-27646

If you have any questions, please state the report number and date

Date: 18.09.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4