



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202501-29216

If you have any questions, please state the report number and date

Date: 30.01.2025

Report

Subject	Report
Inspection date/location	30.01.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	B-W1067
Vehicle Identification Number	WV1ZZZ2KZKX112321

REPORTNUMBER: 202501-29216

If you have any questions, please state the report number and date

Date: 30.01.2025

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	30.01.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	B-W1067
Vehicle type	Van
Manufacturer	VW
Model / Sales description	Caddy 1.4TSI Maxi
Key numbers HSN/TSN	0603 / BXK
Vehicle identification number	WV1ZZZ2KZKX112321
Previous owners	1
First registration	04.06.2019
Mileage	124.455 km
Colour / Colour Code	Weiss
Fuel Type	Petrol
Cubic Capacity / Power	1.395 cm ³ / 92 kW
Number of doors / seats	4 / 2
Transmission	Automatic transmission
Number of keys	2
Last maintenance	Unknown
Next vehicle inspection	01.10.2025
Service documentation	Nonexistent
Trailer coupling	No
Rain sensor	Unavailable
Operating manual	Available
Repainting	Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202501-29216

If you have any questions, please state the report number and date

Date: 30.01.2025

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/55 R16 front axle	All-season tyre on Steel rim	5/5
#2 205/55 R16 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Slight	
2	Bumper rear	Scratch	Slight	
3	Mirror cap right	Scratch	Severe	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Engine bonnet; ~ 240µm
- Roof; ~ 150µm
- Tailgate; ~ 770µm
- Fender le.; ~ 310µm
- Door f.l.; ~ 400µm
- Door r.l.; ~ 1270µm
- Side panel le.; ~ 320µm
- Fender ri.; ~ 300µm
- Door f.r.; ~ 360µm
- Door r.r.; ~ 300µm

REPORTNUMBER: 202501-29216

If you have any questions, please state the report number and date

Date: 30.01.2025

- Side panel ri.; ~ 300µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 30.01.2025



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 14 overview pictures, 3 damage pictures

REPORTNUMBER: 202501-29216

If you have any questions, please state the report number and date

Date: 30.01.2025

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202501-29216

If you have any questions, please state the report number and date

Date: 30.01.2025



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202501-29216

If you have any questions, please state the report number and date

Date: 30.01.2025



Image 13



Image 14

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.21



Image 3: Siehe Pos.3