



Gerlach & Schröder GbR  
Nürnberger Str. 34  
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022

## Report

<b>Subject</b>	Report
<b>Inspection date/location</b>	09.06.2022   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Registration number</b>	
<b>Vehicle Identification Number</b>	WDD2052871F219820

REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022

## Report

<b>Subject</b>	Report
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Inspection date/location</b>	09.06.2022   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Registration number</b>	
<b>Vehicle type</b>	Estate Car
<b>Manufacturer</b>	Mercedes-Benz
<b>Model / Sales description</b>	C63S AMG
<b>Key numbers HSN/TSN</b>	/
<b>Vehicle identification number</b>	WDD2052871F219820
<b>Previous owners</b>	
<b>First registration</b>	08.07.2015
<b>Mileage</b>	104.294 km
<b>Colour / Colour Code</b>	
<b>Fuel Type</b>	Petrol
<b>Cubic Capacity / Power</b>	/
<b>Number of doors / seats</b>	5 / 5
<b>Transmission</b>	Automatic transmission
<b>Number of keys</b>	2
<b>Last maintenance</b>	12.11.2020 / 99.133 km
<b>Next vehicle inspection</b>	
<b>Service documentation</b>	Available
<b>Trailer coupling</b>	No
<b>Rain sensor</b>	Available
<b>Repainting</b>	Found Plastic parts could not be evaluated by means of paint thickness measurement.
<b>Inspection Condition</b>	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022

### Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 245/35 R19 front axle	Summer tyre on Aluminium rim	6/6
#2 265/35 R19 rear axle		2/2

### Brakes

	Front axle	Rear axle
Lining	good	adequate
Disc	good	adequate

### Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bumper front	Stone chip	Slight	
2	Bonnet	Stone chip	Slight	
3	Windshield	Stone chip	Slight	
4	Door panel FL		Slight	
5	Seat FL		Severe	
6			Slight	
7	Aluminium rim RL		Slight	
8	Bumper rear		Slight	
9	Tailgate panel		Slight	
10	Door panel RR		Slight	
11	Aluminium rim RR		Slight	
12	Aluminium rim FR		Slight	
13	Tire FR		Severe	

REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022

14

Slight

## Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired. Essentially, the following vehicle parts were replaced or repaired:

- Engine bonnet; ~ 255µm
- Fender le.; ~ 220µm
- Door f.l.; ~ 160µm
- Side panel le.; ~ 210µm
- Tailgate; ~ 170µm
- Fender ri.; ~ 180µm
- Door f.r.; ~ 165µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

## Test drive / Inspection

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

## Other information

Bebra 20.06.2022



---

Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

**Attached:** 15 overview pictures, 14 damage pictures

REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022

## Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022



Image 13



Image 14



Image 15

## Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022



**Image 3: Siehe Pos.3**



**Image 4: Siehe Pos.4**



**Image 5: Siehe Pos.5**



**Image 6: Siehe Pos.6**



**Image 7: Siehe Pos.7**



**Image 8: Siehe Pos.8**



REPORTNUMBER: 202206-19481

If you have any questions, please state the report number and date

Date: 20.06.2022



Image 9: Siehe Pos.9



Image 10: Siehe Pos.10



Image 11: Siehe Pos.11



Image 12: Siehe Pos.12



Image 13: Siehe Pos.13



Image 14: Siehe Pos.14