



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024

Report

Subject	Report
Inspection date/location	03.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	RO-DS 440
Vehicle Identification Number	6FPPXXMJ2PFC44660



REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	03.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	RO-DS 440
Vehicle type	SUV/Off-road Vehicle/Pickup Truck
Manufacturer	Ford
Model / Sales description	Ranger Doppelkabine 4x4 Wildtrak 3,2 TDCI
Key numbers HSN/TSN	1566 / AAC
Vehicle identification number	6FPPXXMJ2PFC44660
Previous owners	2
First registration	13.04.2015
Mileage	87.808 km
Colour / Colour Code	grau
Fuel Type	Diesel
Cubic Capacity / Power	3.198 cm ³ / 147 kW
Number of doors / seats	4 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	30.04.2021 / 66.743 km
Next vehicle inspection	01.04.2023
Service documentation	Available
Trailer coupling	Fix
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 265/75 R16 front axle	All-season tyre on Steel rim	8/7
#2 265/75 R16 rear axle		8/8

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	Not detectable
Disc	adequate	Drum brakes

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bumper front	Stone chip	Slight	
2	Bonnet		Medium	
3	Fender le		Slight	
4	Door FL		Slight	
5	Door panel FL		Slight	
6	Seat FL		Severe	
7			Medium	
8			Slight	
9	Door RL		Slight	
10	Door panel RL		Slight	
11		Paint chipping	Slight	
12	Side panel right		Slight	

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024

13	Fender ri	Scratch	Slight
14	Door FR		Medium
15	Door RR		Medium
16	Side panel right	Scratch	Medium
17	Tailgate		Medium

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Bumper fr.;
- Engine bonnet; ~ 150µm
- Fender le; ~ 155µm
- Fender ri.; ~ 155µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 04.05.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024

Attached: 18 overview pictures, 17 damage pictures

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 13



Image 14



Image 15



Image 16



Image 17




Image 18

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 7: Siehe Pos.7



Image 8: Siehe Pos.8



Image 9: Siehe Pos.9



Image 10: Siehe Pos.10



Image 11: Siehe Pos.11



Image 12: Siehe Pos.12

REPORTNUMBER: 202405-26179

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 13: Siehe Pos.13



Image 14: Siehe Pos.14



Image 15: Siehe Pos.15



Image 16: Siehe Pos.16



Image 17: Siehe Pos.17