



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25778

If you have any questions, please state the report number and date

Date: 03.04.2024

Report

Subject	Report
Inspection date/location	03.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	EU-AR 9522
Vehicle Identification Number	WBA11FY090FR20163



REPORTNUMBER: 202404-25778

If you have any questions, please state the report number and date

Date: 03.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	03.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	EU-AR 9522
Vehicle type	Estate Car
Manufacturer	BMW
Model / Sales description	318 i M Sport
Key numbers HSN/TSN	0005 / CYW
Vehicle identification number	WBA11FY090FR20163
Previous owners	1
First registration	19.06.2023
Mileage	10.197 km
Colour / Colour Code	schwarz
Fuel Type	Petrol
Cubic Capacity / Power	1.998 cm ³ / 115 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	05.06.2023 / 5 km
Next vehicle inspection	01.06.2024
Service documentation	Electronically
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202404-25778

If you have any questions, please state the report number and date

Date: 03.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/45 R18 front axle	Summer tyre on Aluminium rim	5/5
#2 255/40 R18 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim FR	Scratch	Slight	
2	Windshield	Stone chip	Slight	
3	Bonnet	Stone chip	Slight	
4	Door FL	Scratch	Slight	
5	Bumper rear	Scratch	Slight	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Engine bonnet; ~ 230µm
- Roof; ~ 190µm
- Bumper re.; ~ 160µm
- Fender le; ~ 180µm
- Door f.l.; ~ 190µm
- Door r.l.; ~ 200µm

REPORTNUMBER: 202404-25778

If you have any questions, please state the report number and date

Date: 03.04.2024

- Side panel le.; ~ 290µm
- Fender ri.; ~ 180µm
- Door f.r.; ~ 190µm
- Door r.r.; ~ 180µm
- Side panel ri.; ~ 190µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 03.04.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 6 damage pictures

REPORTNUMBER: 202404-25778

If you have any questions, please state the report number and date

Date: 03.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-25778

If you have any questions, please state the report number and date

Date: 03.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-25778

If you have any questions, please state the report number and date

Date: 03.04.2024



Image 13



Image 14



Image 15



Image 16

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.1

REPORTNUMBER: 202404-25778

If you have any questions, please state the report number and date

Date: 03.04.2024



Image 3: Siehe Pos.2



Image 4: Siehe Pos.3



Image 5: Siehe Pos.4



Image 6: Siehe Pos.5