



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202502-29245

If you have any questions, please state the report number and date

Date: 03.02.2025

Report

Subject	Report
Inspection date/location	31.01.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	MZ-DA620
Vehicle Identification Number	WAUZZZF29LN094023



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202502-29245

If you have any questions, please state the report number and date

Date: 03.02.2025

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	31.01.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	MZ-DA620
Vehicle type	Estate Car
Manufacturer	Audi
Model / Sales description	A6 Avant 50 TDI quattro tiptronic design
Key numbers HSN/TSN	0588 / BSU
Vehicle identification number	WAUZZZF29LN094023
Previous owners	1
First registration	03.09.2020
Mileage	135.889 km
Colour / Colour Code	SCHWARZ
Fuel Type	Hybrid/Diesel
Cubic Capacity / Power	2.967 cm ³ / 210 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	30.08.2024 / 120.235 km
Next vehicle inspection	01.09.2025
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202502-29245

If you have any questions, please state the report number and date

Date: 03.02.2025

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/55 R18 front axle	Summer tyre on Aluminium rim	4/4
#2 225/55 R18 rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bonnet	Scratch	Slight	
3	Bumper front	Stone chip	Slight	
4	Door FR	Scratch	Slight	
5	Bumper rear	Scratch	Slight	
6	Door FL	Scratch	Slight	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Fender ri.; ~ 200µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

REPORTNUMBER: 202502-29245

If you have any questions, please state the report number and date

Date: 03.02.2025

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 03.02.2025



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 7 damage pictures

REPORTNUMBER: 202502-29245

If you have any questions, please state the report number and date

Date: 03.02.2025

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202502-29245

If you have any questions, please state the report number and date

Date: 03.02.2025



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202502-29245

If you have any questions, please state the report number and date

Date: 03.02.2025



Image 13



Image 14

Seite 4 von 4

Nr.	Fzg. Annahmedatum	km-Stand	Serviceberater	
LN094023	13.08.2024	120235	Lucas Lattich	
Mit-arbeiter	Einzel-preis	Menge/Zeit	Beitrag EUR	
			2.367,97	
%-Mwst	Mwst	Steuerbasis-MWst	Mwst-Arswin	Gesamtbetrag
19%	449,91	0,00	0,00	2.817,88

Zahlungsziel: Kredit / sofort fällig

Image 15

Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2

REPORTNUMBER: 202502-29245

If you have any questions, please state the report number and date

Date: 03.02.2025



Image 3: siehe pos.3



Image 4: siehe pos.4



Image 5: siehe pos.5



Image 6: siehe pos.6



Image 7: siehe pos.7