

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25940

If you have any questions, please state the report number and date

Date: 15.04.2024

Report

Subject Inspection date/location

Client Registration number Vehicle Identification Number Report 15.04.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra

WF01XXERK1LB47675



Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25940

If you have any questions, please state the report number and date

Date: 15.04.2024

Report

Subject Report Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra 15.04.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2, Inspection date/location DE-36179 Bebra **Registration number** Vehicle type Estate Car Manufacturer Ford Model / Sales description Ecosport 1.5 ECOBLUE Key numbers HSN/TSN 1 Vehicle identification number WF01XXERK1LB47675 **Previous owners First registration** 13.03.2020 174.036 km Mileage **Colour / Colour Code** SILBER Fuel Type Diesel **Cubic Capacity / Power** 1.496 cm³ / 88 kW Number of doors / seats 5/5Transmission Manual gearbox Number of kevs 1 Last maintenance Unknown Next vehicle inspection 01.03.2025 Service documentation Nonexistent **Trailer coupling** No **Rain sensor** Available **Operating manual** Available Repainting Not Found Plastic parts could not be evaluated by means of paint thickness measurement. **Inspection Condition** non-dismantled, roadworthy, traffic safe



If you have any questions, please state the report number and date

Date: 15.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/50 R17 front axle #2 205/50 R17 rear axle	Summer tyre on Aluminium rim	3/3 5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Door FR	Scratch	Slight	
4	Bumper rear	Scratch	Slight	
5	Tailgate panel	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.



If you have any questions, please state the report number and date

Date: 15.04.2024

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 15.04.2024

Anne

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 13 overview pictures, 4 damage pictures



If you have any questions, please state the report number and date

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

Date: 15.04.2024

Overview pictures



Image 1



Image 3



Image 5



Image 2



Image 4



Image 6



If you have any questions, please state the report number and date

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

Date: 15.04.2024



Image 7





Image 11



Image 8





Image 12



Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25940

If you have any questions, please state the report number and date

Date: 15.04.2024



Image 13

Damage pictures



Image 1: siehe pos.1



Image 3: siehe pos.3



Image 2: siehe pos.2



Image 4: siehe pos.4