



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202412-28678

If you have any questions, please state the report number and date

Date: 06.12.2024

Report

Subject	Report
Inspection date/location	06.12.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	GD-MV 2000
Vehicle Identification Number	KMTGE411PNU003236

REPORTNUMBER: 202412-28678

If you have any questions, please state the report number and date

Date: 06.12.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	06.12.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	GD-MV 2000
Vehicle type	Saloon
Manufacturer	Genesis
Model / Sales description	G80 Luxury Electrified
Key numbers HSN/TSN	8252 / AKR
Vehicle identification number	KMTGE411PNU003236
Previous owners	1
First registration	04.10.2022
Mileage	39.666 km
Colour / Colour Code	BLAU
Fuel Type	Electric
Cubic Capacity / Power	/ 45 kW
Number of doors / seats	4 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	Unknown
Next vehicle inspection	30.10.2025
Service documentation	Nonexistent
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202412-28678

If you have any questions, please state the report number and date

Date: 06.12.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 245/45 R19 front axle	Winter tyre on Aluminium rim	4/4
#2 275/40 R19 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

REPORTNUMBER: 202412-28678

If you have any questions, please state the report number and date

Date: 06.12.2024

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 06.12.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 0 overview pictures, 2 damage pictures

REPORTNUMBER: 202412-28678

If you have any questions, please state the report number and date

Date: 06.12.2024

Overview pictures

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2