



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024

Report

Subject	Report
Inspection date/location	04.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	DU-XD 1030
Vehicle Identification Number	WDF44760113579886



REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	04.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	DU-XD 1030
Vehicle type	Minivan/Minibus
Manufacturer	Mercedes-Benz
Model / Sales description	Vito 116 CDI Komp.120 Aut.
Key numbers HSN/TSN	1313 / BQK
Vehicle identification number	WDF44760113579886
Previous owners	1
First registration	27.03.2019
Mileage	214.599 km
Colour / Colour Code	GELB
Fuel Type	Diesel
Cubic Capacity / Power	2.143 cm ³ / 120 kW
Number of doors / seats	5 / 2
Transmission	Automatic transmission
Number of keys	2
Last maintenance	Unknown
Next vehicle inspection	01.04.2025
Service documentation	Nonexistent (Keine Servicenachweise im Fahrzeug)
Trailer coupling	Fix
Rain sensor	Unavailable
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/65 R16 front axle	Winter tyre on Steel rim with wheel cover	10/10
#2 205/65 R16 rear axle		10/10

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet		Medium	
2	Windshield	Stone chip	Slight	
3	Roof	Stone chip	Slight	
4	Fender le		Medium	
5	Door FL		Slight	
6	Door entry FL		Medium	
7	Side panel left		Medium	
8	Fender ri		Medium	
9	A-pillar right	Stone chip	Slight	
10	Door RR		Medium	
11	Side panel right		Medium	
12			Medium	

REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024

13	Medium
14 Bumper rear	Medium

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Door f.r.; ~ 265µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 04.05.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 14 damage pictures

REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 13



Image 14



Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.7



Image 8: Siehe Pos.8

REPORTNUMBER: 202405-26185

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 9: Siehe Pos.9



Image 10: Siehe Pos.10



Image 11: Siehe Pos.11



Image 12: Siehe Pos.12



Image 13: Siehe Pos.13



Image 14: Siehe Pos.14