



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202501-29119

If you have any questions, please state the report number and date

Date: 23.01.2025

Report

Subject	Report
Inspection date/location	22.01.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	NE-MO442
Vehicle Identification Number	WAUZZZF45MA033696

REPORTNUMBER: 202501-29119

If you have any questions, please state the report number and date

Date: 23.01.2025

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	22.01.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	NE-MO442
Vehicle type	Saloon
Manufacturer	Audi
Model / Sales description	A4 40 TDI 140
Key numbers HSN/TSN	0588 / BWI
Vehicle identification number	WAUZZZF45MA033696
Previous owners	1
First registration	06.01.2021
Mileage	124.969 km
Colour / Colour Code	Grün
Fuel Type	Hybrid/Diesel
Cubic Capacity / Power	1.968 cm ³ / 150 kW
Number of doors / seats	4 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	16.08.2024 / 116.300 km
Next vehicle inspection	01.03.2026
Service documentation	Available
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202501-29119

If you have any questions, please state the report number and date

Date: 23.01.2025

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 245/40 R18 front axle	Summer tyre on Aluminium rim	3/5
#2 245/40 R18 rear axle		2/1

The state of the tyres is not roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Slight	
2	Bonnet	Stone chip	Slight	
3	Mirror cap left	Stone chip	Slight	
4	Door FL	Scratch	Slight	
5	Side panel left	Dent	Slight	
6	Door FR	Scratch	Slight	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Bumper fr.;
- Engine bonnet; ~ 170µm
- Fender le; ~ 170µm
- Door f.r.; ~ 190µm

REPORTNUMBER: 202501-29119

If you have any questions, please state the report number and date

Date: 23.01.2025

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 23.01.2025



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 6 damage pictures

REPORTNUMBER: 202501-29119

If you have any questions, please state the report number and date

Date: 23.01.2025

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202501-29119

If you have any questions, please state the report number and date

Date: 23.01.2025



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202501-29119

If you have any questions, please state the report number and date

Date: 23.01.2025



Image 13



Image 14



Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202501-29119

If you have any questions, please state the report number and date

Date: 23.01.2025



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6