



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-26105

If you have any questions, please state the report number and date

Date: 29.04.2024

Report

Subject	Report
Inspection date/location	27.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	KN-DM93
Vehicle Identification Number	WAUZZZF50KA082231



REPORTNUMBER: 202404-26105

If you have any questions, please state the report number and date

Date: 29.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	27.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	KN-DM93
Vehicle type	Saloon
Manufacturer	Audi
Model / Sales description	A5 SB 40 TFSI
Key numbers HSN/TSN	0588 / BMR
Vehicle identification number	WAUZZZF50KA082231
Previous owners	1
First registration	25.10.2019
Mileage	77.754 km
Colour / Colour Code	grau
Fuel Type	Hybrid/Petrol
Cubic Capacity / Power	1.984 cm ³ / 140 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	17.11.2022 / 55.772 km
Next vehicle inspection	01.11.2024
Service documentation	Available
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202404-26105

If you have any questions, please state the report number and date

Date: 29.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/50 R17 front axle	Summer tyre on Aluminium rim	3/3
#2 225/50 R17 rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bumper front		Medium	
2	Bonnet	Stone chip	Slight	
3	Windshield	Stone chip	Medium	
4	Roof		Slight	
5	Door FL	Scratch	Slight	
6	Seat FL		Slight	
7	Tail light left	Scratch	Severe	
8	Door RR	Scratch	Severe	
9	Tailgate	Scratch	Severe	
10	Bumper rear		Slight	

REPORTNUMBER: 202404-26105

If you have any questions, please state the report number and date

Date: 29.04.2024

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Side panel le.; ~ 175µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 29.04.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 14 overview pictures, 10 damage pictures

REPORTNUMBER: 202404-26105

If you have any questions, please state the report number and date

Date: 29.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-26105

If you have any questions, please state the report number and date

Date: 29.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-26105

If you have any questions, please state the report number and date

Date: 29.04.2024



Image 13



Image 14

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4

REPORTNUMBER: 202404-26105

If you have any questions, please state the report number and date

Date: 29.04.2024



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.7



Image 8: Siehe Pos.8



Image 9: Siehe Pos.9



Image 10: Siehe Pos.10