

Date: 20.04.2024

REPORTNUMBER: 202404-26003

If you have any questions, please state the report number and date

Report

Subject Report

Inspection date/location 19.04.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2,

DE-36179 Bebra

Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra

Registration number HH-UL6200

Vehicle Identification Number WBA6L51000FJ38256

20.04.2024 VIN: WBA6L51000FJ38256; Report number: 202404-26003 Page 1 of 8

Date: 20.04.2024

REPORTNUMBER: 202404-26003

If you have any questions, please state the report number and date

Report

Subject Report

Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra 19.04.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2,

DE-36179 Bebra

Registration numberHH-UL6200Vehicle typeEstate CarManufacturerBMW

Model / Sales description 320d Touring Luxury Line

Key numbers HSN/TSN 0005 / CWA

Vehicle identification number WBA6L51000FJ38256

Previous owners 1

First registration 30.01.2020 **Mileage** 122.261 km

Colour / Colour Code weiß
Fuel Type Diesel

Cubic Capacity / Power 1.995 cm³ / 140 kW

Number of doors / seats 5 / 5

Transmission Automatic transmission

Number of keys 2

Last maintenance 16.11.2023 / 115.993 km

Next vehicle inspection 01.04.2025
Service documentation Available
Trailer coupling No

Rain sensorAvailableOperating manualAvailableRepaintingFound

Plastic parts could not be evaluated by means of paint

thickness measurement.

Inspection Condition non-dismantled, roadworthy, traffic safe

20.04.2024 VIN: WBA6L51000FJ38256; Report number: 202404-26003 Page 2 of 8

REPORTNUMBER: 202404-26003

If you have any questions, please state the report number and date Date: 20.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/45 R18 front axle	Summer tyre on Aluminium rim	6/6
#2 255/40 R18 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bumper front	Stone chip	Slight	
2	Side panel left	Dent	Slight	
3	Bumper rear	Scratch	Slight	
4	Door FR	Stone chip	Slight	
5	Fender ri	Stone chip	Slight	
6	Aluminium rim FR	Scratch	Medium	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Engine bonnet; ~ 370µm
- Roof; ~ 220µm
- Tailgate; ~ 200µm
- Fender le; ~ 200µm
- Door f.l.; ~ 250µm

20.04.2024 VIN: WBA6L51000FJ38256; Report number: 202404-26003 Page 3 of 8

Date: 20.04.2024

REPORTNUMBER: 202404-26003

If you have any questions, please state the report number and date

- Door r.l.; ~ 320µm

- Side panel le.; ~ 400µm

- Fender ri.; ~ 220µm

- Door f.r.; ~ 230µm

- Door r.r.; ~ 220µm

- Side panel ri.; ~ 180µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 20.04.2024

Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 6 damage pictures

20.04.2024 VIN: WBA6L51000FJ38256; Report number: 202404-26003 Page 4 of 8

Date: 20.04.2024

REPORTNUMBER: 202404-26003

If you have any questions, please state the report number and date

Overview pictures



Image 1



Image 3



Image 5



Image 2



Image 4



Image 6

20.04.2024 VIN: WBA6L51000FJ38256; Report number: 202404-26003 Page 5 of 8

Date: 20.04.2024

REPORTNUMBER: 202404-26003

If you have any questions, please state the report number and date



Image 7



Image 9



Image 11



Image 8



Image 10



Image 12

20.04.2024 VIN: WBA6L51000FJ38256; Report number: 202404-26003 Page 6 of 8

Date: 20.04.2024

REPORTNUMBER: 202404-26003

If you have any questions, please state the report number and date



Image 13



Image 15



Image 14



Image 16

Damage pictures



Image 1: Siehe Pos.1




Image 2: Siehe Pos.2

20.04.2024 VIN: WBA6L51000FJ38256; Report number: 202404-26003 Page 7 of 8

Date: 20.04.2024

REPORTNUMBER: 202404-26003

If you have any questions, please state the report number and date



Image 3: Siehe Pos.3



Image 5: Siehe Pos.5



Image 4: Siehe Pos.4



Image 6: Siehe Pos.6

20.04.2024 VIN: WBA6L51000FJ38256; Report number: 202404-26003 Page 8 of 8