



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202502-29268

If you have any questions, please state the report number and date

Date: 04.02.2025

Report

Subject	Report
Inspection date/location	04.02.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	WÜ-KW670E
Vehicle Identification Number	LSJWH4090NN195843

REPORTNUMBER: 202502-29268

If you have any questions, please state the report number and date

Date: 04.02.2025

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	04.02.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	WÜ-KW670E
Vehicle type	Saloon
Manufacturer	MG
Model / Sales description	MG4 Standard 125
Key numbers HSN/TSN	2180 / AAL
Vehicle identification number	LSJWH4090NN195843
Previous owners	1
First registration	06.12.2022
Mileage	13.287 km
Colour / Colour Code	grau
Fuel Type	Electric
Cubic Capacity / Power	/ 54 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	Unknown
Next vehicle inspection	01.12.2025
Service documentation	Nonexistent
Trailer coupling	No
Rain sensor	Available
Operating manual	Unavailable
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202502-29268

If you have any questions, please state the report number and date

Date: 04.02.2025

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/60 R16 front axle	Summer tyre on Steel rim with wheel cover	5/5
#2 205/60 R16 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Mirror cap left	Stone chip	Slight	
4	Bumper rear	Scratch	Slight	
5	Mirror cap right	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202502-29268

If you have any questions, please state the report number and date

Date: 04.02.2025

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 04.02.2025



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 5 damage pictures

REPORTNUMBER: 202502-29268

If you have any questions, please state the report number and date

Date: 04.02.2025

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202502-29268

If you have any questions, please state the report number and date

Date: 04.02.2025



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202502-29268

If you have any questions, please state the report number and date

Date: 04.02.2025



Image 13



Image 14



Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202502-29268

If you have any questions, please state the report number and date

Date: 04.02.2025



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5