



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024

Report

Subject	Report
Inspection date/location	06.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	HH-HG3750
Vehicle Identification Number	W1V9076331P208176



REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	06.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	HH-HG3750
Vehicle type	Minivan/Minibus
Manufacturer	Mercedes-Benz
Model / Sales description	311 CDI Sprinter 3665 HA HD
Key numbers HSN/TSN	2222 / 000
Vehicle identification number	W1V9076331P208176
Previous owners	1
First registration	10.02.2020
Mileage	49.611 km
Colour / Colour Code	WEISS
Fuel Type	Diesel
Cubic Capacity / Power	2.143 cm ³ / 84 kW
Number of doors / seats	5 / 2
Transmission	Manual gearbox
Number of keys	1
Last maintenance	Unknown
Next vehicle inspection	01.03.2024
Service documentation	Nonexistent (Keine Servicenachweise im Fahrzeug)
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 235/65 R16 front axle	All-season tyre on Steel rim with wheel cover	9/9
#2 235/65 R16 rear axle		9/8

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bumper front		Slight	
2	Bonnet		Medium	
3	Roof		Slight	
4	Fender ri		Slight	
5	Door FL		Slight	
6		Dent	Slight	
7	Seat FL		Slight	
8	Side panel left		Slight	
9	Door FR		Slight	
10	Door RR		Slight	
11	Side panel right		Slight	
12			Slight	

REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024

13

Slight

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 06.04.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 13 damage pictures

REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024



Image 13



Image 14



Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.7



Image 8: Siehe Pos.8



Image 9: Siehe Pos.9



Image 10: Siehe Pos.10

REPORTNUMBER: 202404-25830

If you have any questions, please state the report number and date

Date: 06.04.2024



Image 11: Siehe Pos.11



Image 12: Siehe Pos.12



Image 13: Siehe Pos.13