



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26184

If you have any questions, please state the report number and date

Date: 04.05.2024

Report

Subject	Report
Inspection date/location	04.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	M-TR3805
Vehicle Identification Number	W1V9106331P467715



REPORTNUMBER: 202405-26184

If you have any questions, please state the report number and date

Date: 04.05.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	04.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	M-TR3805
Vehicle type	Minivan/Minibus
Manufacturer	Mercedes-Benz
Model / Sales description	Sprinter 315 CDI Stan.VA
Key numbers HSN/TSN	2222 / BFF
Vehicle identification number	W1V9106331P467715
Previous owners	1
First registration	17.11.2022
Mileage	6.628 km
Colour / Colour Code	GRAU
Fuel Type	Diesel
Cubic Capacity / Power	1.950 cm ³ / 110 kW
Number of doors / seats	5 / 4
Transmission	Automatic transmission
Number of keys	1
Last maintenance	Unknown
Next vehicle inspection	01.11.2023
Service documentation	Nonexistent (Kein Servicenachweis im Fahrzeug)
Trailer coupling	No
Rain sensor	Available
Operating manual	Unavailable
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202405-26184

If you have any questions, please state the report number and date

Date: 04.05.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/65 R16 front axle	All-season tyre on Steel rim with wheel cover	3/2
#2 225/65 R16 rear axle		7/7

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	good
Disc	adequate	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Fender le	Scratch	Slight	
2	Door FL		Slight	
3			Slight	
4	Side panel left		Slight	
5	Side panel right		Medium	
6			Slight	
7	Bumper rear		Slight	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Side panel le.; ~ 1350µm

A sample-like paint thickness measurement showed an increased paint thickness, which is

REPORTNUMBER: 202405-26184

If you have any questions, please state the report number and date

Date: 04.05.2024

almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 04.05.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 7 damage pictures

REPORTNUMBER: 202405-26184

If you have any questions, please state the report number and date

Date: 04.05.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202405-26184

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202405-26184

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 13



Image 14



Image 15



Image 16

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202405-26184

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.7