



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023

Report

Subject	Report
Inspection date/location	21.09.2023 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	MKK-O 1367
Vehicle Identification Number	WDF63981313771996



REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	21.09.2023 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	MKK-O 1367
Vehicle type	Minivan/Minibus
Manufacturer	Mercedes-Benz
Model / Sales description	Viano
Key numbers HSN/TSN	1313 / BPR
Vehicle identification number	WDF63981313771996
Previous owners	3
First registration	05.10.2012
Mileage	164.466 km
Colour / Colour Code	
Fuel Type	Diesel
Cubic Capacity / Power	/ 165 kW
Number of doors / seats	5 / 6
Transmission	Automatic transmission
Number of keys	2
Last maintenance	18.01.2021 / 134.000 km
Next vehicle inspection	01.05.2025
Service documentation	Available
Trailer coupling	Detachable
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/55 R17 front axle	All-season tyre on Aluminium rim	5/5
#2 225/55 R17 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Fender ri	Scratch	Slight	
4	Door FR	Scratch	Slight	
5	Door RR	Scratch	Slight	
6	Tailgate	Crack	Medium	
7	Bumper rear	Scratch	Slight	
8	Tailgate panel	Scratch	Slight	
9	Side panel left	Scratch	Slight	
10	Door RL	Scratch	Slight	
11	Door FL	Scratch	Slight	
12	Door entry FL	Scratch	Slight	

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023

13	Mirror cap left	Scratch	Slight
14	Fender le	Stone chip	Slight
15	Aluminium rim FL	Scratch	Medium

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Tailgate; ~ 1050µm
- Side panel ri.; ~ 180µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 21.09.2023



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 16 damage pictures

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023



Image 13



Image 14




Image 15



Image 16

Damage pictures




Image 1: siehe pos.1




Image 2: siehe pos.2

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023



Image 3: siehe pos.3



Image 4: siehe pos.4



Image 5: siehe pos.5



Image 6: siehe pos.5.1



Image 7: siehe pos.6



Image 8: siehe pos.7

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023



Image 9: siehe pos.8



Image 10: siehe pos.9



Image 11: siehe pos.10



Image 12: siehe pos.11



Image 13: siehe pos.12



Image 14: siehe pos.13

REPORTNUMBER: 202309-23610

If you have any questions, please state the report number and date

Date: 21.09.2023



Image 15: siehe pos.14



Image 16: siehe pos.15