



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202409-27603

If you have any questions, please state the report number and date

Date: 17.09.2024

Report

Subject	Report
Inspection date/location	13.09.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	HR-MN 2021
Vehicle Identification Number	WBACR6107L9C65051

REPORTNUMBER: 202409-27603

If you have any questions, please state the report number and date

Date: 17.09.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	13.09.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	HR-MN 2021
Vehicle type	SUV/Off-road Vehicle/Pickup Truck
Manufacturer	BMW
Model / Sales description	X5 4.0i XDrive M-Sport
Key numbers HSN/TSN	0005 / CSZ
Vehicle identification number	WBACR6107L9C65051
Previous owners	
First registration	20.05.2020
Mileage	123.020 km
Colour / Colour Code	schwarz
Fuel Type	Petrol
Cubic Capacity / Power	2.998 cm ³ / 250 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	22.03.2022 / 60.343 km
Next vehicle inspection	30.01.2025
Service documentation	Available
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202409-27603

If you have any questions, please state the report number and date

Date: 17.09.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 275/40 R21 front axle	Summer tyre on Aluminium rim	7/7
#2 215/35 R21 rear axle		7/7

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Bumper rear	Scratch	Slight	
4	Side panel left	Scratch	Slight	
5	Door FL	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202409-27603

If you have any questions, please state the report number and date

Date: 17.09.2024

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 17.09.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 1 overview pictures, 5 damage pictures

REPORTNUMBER: 202409-27603

If you have any questions, please state the report number and date

Date: 17.09.2024

Overview pictures




Image 1

Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2



Image 3: siehe pos.3



Image 4: siehe pos.4

REPORTNUMBER: 202409-27603

If you have any questions, please state the report number and date

Date: 17.09.2024



Image 5: siehe pos.5