Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202610-34887

If you have any questions, please state the report number and date

Date: 23.10.2026

Report

Subject	Report
Inspection date/location	22.10.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	HEF IW 6
Vehicle Identification Number	WBA11AW080FM20937

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202610-34887

If you have any questions, please state the report number and date

Date: 23.10.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	22.10.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	HEF IW 6
Vehicle type	Sports Car/Coupe
Manufacturer	BMW
Model / Sales description	M440
Key numbers HSN/TSN	0005 / DFZ
Vehicle identification number	WBA11AW080FM20937
Previous owners	2
First registration	13.04.2022
Mileage	62.781 km
Colour / Colour Code	weiß
Fuel Type	Petrol
Cubic Capacity / Power	2.998 cm³ / 275 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	13.02.2026 / 55.783 km
Next vehicle inspection	01.05.2028
Service documentation	Electronically
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

Tires / Rims

Axis / Size		Tires	Profile [mm]
#1 245/35 R20	front axle	Summer tyre on Aluminium rim	4/4
#2 255/35 R19	rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim FR	Scratch	Medium	
2	Windshield	Stone chip	Normal wear and tear for age and mileage	
3	Bonnet	Stone chip	Normal wear and tear for age and mileage	
4	Mirror cap left	Stone chip	Normal wear and tear for age and mileage	
5	Mirror cap right	Stone chip	Normal wear and tear for age and mileage	

Previous damages / Repaintings

The vehicle was found to have been repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Bumper fr.;

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202610-34887

If you have any questions, please state the report number and date

Date: 23.10.2026

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.
The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.
The vehicle underbody was not inspected because the vehicle was not raised on a lift.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 23.10.2026

Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 5 damage pictures

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202610-34887

If you have any questions, please state the report number and date

Date: 23.10.2026

Overview pictures

Image 1

Image 2

Image 3

Image 4

Image 5

Image 6

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202610-34887

If you have any questions, please state the report number and date

Date: 23.10.2026

Image 7

Image 8



Image 9

Image 10



Image 11

Image 12

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202610-34887

If you have any questions, please state the report number and date

Date: 23.10.2026

Image 13

Image 14



Image 15

Image 16

Damage pictures

Image 1: Siehe Pos.1

Image 2: Siehe Pos.2

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202610-34887

If you have any questions, please state the report number and date

Date: 23.10.2026

Image 3: Siehe Pos.3

Image 4: Siehe Pos.4

Image 5: Siehe Pos.5