Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34664

If you have any questions, please state the report number and date

Date: 28.09.2026

Report

Subject	Report
Inspection date/location	28.09.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	RO-MG 5550
Vehicle Identification Number	WBA41EG0005X32050

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34664

If you have any questions, please state the report number and date

Date: 28.09.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	28.09.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	RO-MG 5550
Vehicle type	Estate Car
Manufacturer	BMW
Model / Sales description	X1
Key numbers HSN/TSN	0005 / DJG
Vehicle identification number	WBA41EG0005X32050
Previous owners	1
First registration	05.07.2023
Mileage	117.466 km
Colour / Colour Code	Schwarz
Fuel Type	Diesel
Cubic Capacity / Power	1.995 cm³ / 110 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	30.04.2026 / 114.378 km
Next vehicle inspection	30.07.2026
Service documentation	Available
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34664
If you have any questions, please state the report number and date

Date: 28.09.2026

Tires / Rims

Axis / Size		Tires	Profile [mm]
#1 225/55 R18	front axle	Summer tyre on Aluminium rim	5/5
#2 225/55 R18	rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Normal wear and tear for age and mileage	
2	Bonnet	Stone chip	Normal wear and tear for age and mileage	
3	Bumper front	Stone chip	Normal wear and tear for age and mileage	
4	Mirror cap left	Stone chip	Normal wear and tear for age and mileage	
5	Bumper rear	Scratch	Normal wear and tear for age and mileage	
6	Mirror cap right	Stone chip	Normal wear and tear for age and mileage	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.
Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34664

If you have any questions, please state the report number and date

Date: 28.09.2026

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.
The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.
The vehicle underbody was not inspected because the vehicle was not raised on a lift.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 28.09.2026

Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 7 damage pictures

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34664

If you have any questions, please state the report number and date

Date: 28.09.2026

Overview pictures

Image 1

Image 2

Image 3

Image 4

Image 5

Image 6

KÜS INGENIEURBÜRO für Kfz-Wesen
GERLACH & SCHRÖDER
LISPENHAUSEN

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34664

If you have any questions, please state the report number and date

Date: 28.09.2026

Image 7

Image 8

Image 9

Image 10



Image 11

Image 12

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34664

If you have any questions, please state the report number and date

Date: 28.09.2026

Image 13



Image 14



Image 15



Image 16

Damage pictures

Image 1: Siehe Pos.1

Image 2: Siehe Pos.2

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34664

If you have any questions, please state the report number and date

Date: 28.09.2026



Image 3: Siehe Pos.3

Image 4: Siehe Pos.3

Image 5: Siehe Pos.4

Image 6: Siehe Pos.5

Image 7: Siehe Pos.6