Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34361

If you have any questions, please state the report number and date

Date: 01.09.2026

Report

Subject	Report
Inspection date/location	01.09.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	HH-WS8486
Vehicle Identification Number	WF0PXXGCHPSP14571

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34361

If you have any questions, please state the report number and date

Date: 01.09.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	01.09.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	HH-WS8486
Vehicle type	Estate Car
Manufacturer	Ford
Model / Sales description	FOCUS-TURNIER
Key numbers HSN/TSN	8566 / BYE
Vehicle identification number	WF0PXXGCHPSP14571
Previous owners	1
First registration	23.06.2025
Mileage	28.863 km
Colour / Colour Code	
Fuel Type	Diesel
Cubic Capacity / Power	1.499 cm³ / 85 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	28.04.2026 / 25.674 km
Next vehicle inspection	01.06.2026
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34361
If you have any questions, please state the report number and date

Date: 01.09.2026

Tires / Rims

Axis / Size		Tires	Profile [mm]
#1 215/50 R17	front axle	All-season tyre on Aluminium rim	4/4
#2 215/50 R17	rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Normal wear and tear for age and mileage	
2	Bonnet	Scratch	Medium	
3	Bumper front	Stone chip	Normal wear and tear for age and mileage	
4	Side panel left	Scratch	Slight	
5	Bumper rear	Scratch	Normal wear and tear for age and mileage	
6	Fender ri	Scratch	Severe	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.
Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34361

If you have any questions, please state the report number and date

Date: 01.09.2026

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.
The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.
The vehicle underbody was not inspected because the vehicle was not raised on a lift.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 01.09.2026

Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 6 damage pictures

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34361

If you have any questions, please state the report number and date

Date: 01.09.2026

Overview pictures

Image 1

Image 2

Image 3

Image 4

Image 5

Image 6

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34361

If you have any questions, please state the report number and date

Date: 01.09.2026

Image 7

Image 8

Image 9

Image 10



Image 11

Image 12

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34361

If you have any questions, please state the report number and date

Date: 01.09.2026



Image 13



Image 14



Image 15

Damage pictures



Image 1: Siehe Pos.1

Image 2: Siehe Pos.2

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34361

If you have any questions, please state the report number and date

Date: 01.09.2026

Image 3: Siehe Pos.3

Image 4: Siehe Pos.4

Image 5: Siehe Pos.5

Image 6: Siehe Pos.6