Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34541

If you have any questions, please state the report number and date

Date: 16.09.2026

Report

Subject	Report
Inspection date/location	16.09.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	
Vehicle Identification Number	W1NKM5BBXSU073552

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34541

If you have any questions, please state the report number and date

Date: 16.09.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	16.09.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	
Vehicle type	Estate Car
Manufacturer	Mercedes-Benz
Model / Sales description	GLC 200
Key numbers HSN/TSN	/
Vehicle identification number	W1NKM5BBXSU073552
Previous owners	1
First registration	01.11.2024
Mileage	31.571 km
Colour / Colour Code	SCHWARZ
Fuel Type	Petrol
Cubic Capacity / Power	1.999 cm³ / 167 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	27.01.2026 / 24.357 km
Next vehicle inspection	
Service documentation	Available
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34541
If you have any questions, please state the report number and date

Date: 16.09.2026

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 235/60 R18 front axle	Winter tyre on Aluminium rim	5/5
#2 235/60 R18 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Normal wear and tear for age and mileage	
2	Bumper front	Stone chip	Normal wear and tear for age and mileage	
3	Mirror cap right	Scratch	Slight	
4	Bumper rear	Scratch	Slight	
5	Tailgate	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.
Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34541

If you have any questions, please state the report number and date

Date: 16.09.2026

Test drive / Inspection

There was a short drive on the company site.
A test run of the engine was carried out.
At the time of the inspection the vehicle was not authorized for public roads.
An impairment of traffic safety was not detected.
The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.
The vehicle underbody was not inspected because the vehicle was not raised on a lift.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 16.09.2026

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 5 damage pictures

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34541

If you have any questions, please state the report number and date

Date: 16.09.2026

Overview pictures

Image 1

Image 2

Image 3

Image 4



Image 5

Image 6

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34541

If you have any questions, please state the report number and date

Date: 16.09.2026

Image 7

Image 8



Image 9



Image 10

Image 11



Image 12

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34541

If you have any questions, please state the report number and date

Date: 16.09.2026

Image 13

Image 14



Image 15

Damage pictures

Image 1:

Image 2:

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34541

If you have any questions, please state the report number and date

Date: 16.09.2026

Image 3:

Image 4:

Image 5: