Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329

If you have any questions, please state the report number and date

Date: 28.08.2026

Report

Subject	Report
Inspection date/location	27.08.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	FN-DB1904
Vehicle Identification Number	SAJBB2BN4RCY93603

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329
If you have any questions, please state the report number and date

Date: 28.08.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	27.08.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	FN-DB1904
Vehicle type	Estate Car
Manufacturer	Jaguar
Model / Sales description	XF
Key numbers HSN/TSN	1590 / AJO
Vehicle identification number	SAJBB2BN4RCY93603
Previous owners	1
First registration	19.07.2023
Mileage	87.108 km
Colour / Colour Code	SCHWARZ
Fuel Type	Hybrid/Diesel
Cubic Capacity / Power	1.998 cm³ / 150 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	06.11.2025 / 67.235 km
Next vehicle inspection	01.07.2026
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329
If you have any questions, please state the report number and date

Date: 28.08.2026

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 245/40 R19 front axle	Summer tyre on Aluminium rim	3/2
#2 245/40 R19 rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim FR	Scratch	Severe	
2	Windshield	Stone chip	Normal wear and tear for age and mileage	
3	Bonnet	Stone chip	Normal wear and tear for age and mileage	
4	Bumper front	Stone chip	Normal wear and tear for age and mileage	
5	Mirror cap left	Stone chip	Normal wear and tear for age and mileage	
6	Door RL	Scratch	Normal wear and tear for age and mileage	
7	Bumper rear	Scratch	Normal wear and tear for age and mileage	
8	Tailgate panel	Scratch	Slight	
9	Door entry RR	Scratch	Medium	
10	Door FR	Scratch	Normal wear and tear for age and mileage	
11	Mirror cap right	Stone chip	Normal wear and tear for age and mileage	

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329
If you have any questions, please state the report number and date

Date: 28.08.2026

Previous damages / Repaintings

The vehicle was found to have been repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Side panel le.; ~ 210µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.
The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.
The vehicle underbody was not inspected because the vehicle was not raised on a lift.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 28.08.2026

Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 12 damage pictures

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329

If you have any questions, please state the report number and date

Date: 28.08.2026

Overview pictures

Image 1

Image 2

Image 3

Image 4

Image 5

Image 6

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329

If you have any questions, please state the report number and date

Date: 28.08.2026

Image 7

Image 8

Image 9

Image 10



Image 11



Image 12

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329
If you have any questions, please state the report number and date

Date: 28.08.2026



Image 13



Image 14

Image 15

Damage pictures

Image 1: Siehe Pos.1

Image 2: Siehe Pos.2

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329

If you have any questions, please state the report number and date

Date: 28.08.2026

Image 3: Siehe Pos.3

Image 4: Siehe Pos.4

Image 5: Siehe Pos.4

Image 6: Siehe Pos.5



Image 7: Siehe Pos.6

Image 8: Siehe Pos.7

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202608-34329

If you have any questions, please state the report number and date

Date: 28.08.2026

Image 9: Siehe Pos.8

Image 10: Siehe Pos.9

Image 11: Siehe Pos.10

Image 12: Siehe Pos.11