Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34436

If you have any questions, please state the report number and date

Date: 08.09.2026

Report

Subject	Report
Inspection date/location	07.09.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	F-KM363E
Vehicle Identification Number	TMBJW7NX8NY069786

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34436
If you have any questions, please state the report number and date

Date: 08.09.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	07.09.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	F-KM363E
Vehicle type	Estate Car
Manufacturer	Skoda
Model / Sales description	Octavia
Key numbers HSN/TSN	8004 / AVE
Vehicle identification number	TMBJW7NX8NY069786
Previous owners	1
First registration	21.03.2022
Mileage	107.158 km
Colour / Colour Code	WEISS
Fuel Type	Petrol
Cubic Capacity / Power	1.395 cm³ / 110 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	26.03.2026 / 105.482 km
Next vehicle inspection	30.03.2027
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34436
If you have any questions, please state the report number and date

Date: 08.09.2026

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/45 R18 front axle	Summer tyre on Aluminium rim	5/5
#2 225/45 R18 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Normal wear and tear for age and mileage	
2	Bumper front	Stone chip	Normal wear and tear for age and mileage	
3	Bumper front	Scratch	Medium	
4	Aluminium rim FR	Scratch	Severe	
5	Door RR	Scratch	Slight	
6	Aluminium rim RR	Scratch	Severe	
7	Tailgate panel	Scratch	Slight	
8	Aluminium rim FL	Scratch	Severe	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.
Plastic parts could not be evaluated by means of paint thickness measurement. Thus

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

There was a short drive on the company site.
A test run of the engine was carried out.
At the time of the inspection the vehicle was not authorized for public roads.
An impairment of traffic safety was not detected.
The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.
The vehicle underbody was not inspected because the vehicle was not raised on a lift.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 08.09.2026

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 8 damage pictures

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34436

If you have any questions, please state the report number and date

Date: 08.09.2026

Overview pictures

Image 1

Image 2

Image 3

Image 4

Image 5

Image 6

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34436

If you have any questions, please state the report number and date

Date: 08.09.2026

Image 7

Image 8

Image 9



Image 10

Image 11



Image 12

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34436

If you have any questions, please state the report number and date

Date: 08.09.2026



Image 13



Image 14



Image 15



Image 16

Damage pictures



Image 1:

Image 2:

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202609-34436

If you have any questions, please state the report number and date

Date: 08.09.2026

Image 3:

Image 4:

Image 5:

Image 6:

Image 7:

Image 8: