



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024

Report

Subject	Report
Inspection date/location	26.02.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	DO-IT 6820
Vehicle Identification Number	WAUZZZF48KA085966



REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	26.02.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	DO-IT 6820
Vehicle type	Estate Car
Manufacturer	Audi
Model / Sales description	A4 Avant 3.0 TDI quattro S tronic sport
Key numbers HSN/TSN	0588 / BNZ
Vehicle identification number	WAUZZZF48KA085966
Previous owners	1
First registration	11.06.2019
Mileage	158.790 km
Colour / Colour Code	SCHWARZ
Fuel Type	Diesel
Cubic Capacity / Power	2.967 cm ³ / 170 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	15.09.2023 / 150.350 km
Next vehicle inspection	01.06.2024
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 245/40 R18 front axle	Summer tyre on Aluminium rim	6/6
#2 245/40 R18 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim RL	Scratch	Severe	
2	Aluminium rim FR	Scratch	Severe	
3	Aluminium rim RR	Scratch	Severe	
4	Windshield	Stone chip	Severe	
5	Bonnet	Stone chip	Severe	
6	Bumper front	Stone chip	Severe	
7	Mirror cap left	Stone chip	Slight	
8	Door FL	Scratch	Slight	
9	Bumper rear	Scratch	Slight	
10	Mirror cap right	Stone chip	Slight	
11	Fender ri	Stone chip	Medium	

REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 26.02.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 12 damage pictures

REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024



Image 13



Image 14

Komplettnachweis	
Fahrzeuginformationen	
Fahrzeugsnummer	WAUZZZF48KA085966
Typbezeichnung	A4 Avant (2003) 2.0 TFSI 170 kW
Datum der Auslieferung	2010-01-20
Inspektion	
Datum	2023-09-13
Laufleistung	150350 km
Auftragsnummer	2023004217
Durchgeführt von	Audi Kitzil GmbH Michael Kitzil-Str. 1-3 85715 Unterschleißheim Deutschland
Autorisierter Audi Service Partner	Ja
Mobilitätsgarantie	Ja (bis Anzeige Service)
Ölwechsel-Service (flexibel)	
Datum	2023-08-14
Laufleistung	148229 km
Auftragsnummer	2023005751
Durchgeführt von	Audi Kitzil GmbH Michael Kitzil-Str. 1-3 85715 Unterschleißheim

Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.6



Image 8: Siehe Pos.7

REPORTNUMBER: 202402-25313

If you have any questions, please state the report number and date

Date: 26.02.2024



Image 9: Siehe Pos.8



Image 10: Siehe Pos.9



Image 11: Siehe Pos.10



Image 12: Siehe Pos.11