



Gerlach & Schröder GbR  
Nürnberger Str. 34  
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26245

If you have any questions, please state the report number and date

Date: 10.05.2024

## Report

<b>Subject</b>	Report
<b>Inspection date/location</b>	10.05.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Registration number</b>	HEF-MM 434
<b>Vehicle Identification Number</b>	YF3YC3MFC12J44682



REPORTNUMBER: 202405-26245

If you have any questions, please state the report number and date

Date: 10.05.2024

## Report

<b>Subject</b>	Report
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Inspection date/location</b>	10.05.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Registration number</b>	HEF-MM 434
<b>Vehicle type</b>	Van
<b>Manufacturer</b>	Peugeot
<b>Model / Sales description</b>	Boxer
<b>Key numbers HSN/TSN</b>	3003 / AXJ
<b>Vehicle identification number</b>	YF3YC3MFC12J44682
<b>Previous owners</b>	2
<b>First registration</b>	05.12.2018
<b>Mileage</b>	123.938 km
<b>Colour / Colour Code</b>	Weiss
<b>Fuel Type</b>	Diesel
<b>Cubic Capacity / Power</b>	1.997 cm <sup>3</sup> / 120 kW
<b>Number of doors / seats</b>	4 / 3
<b>Transmission</b>	Manual gearbox
<b>Number of keys</b>	2
<b>Last maintenance</b>	Unknown
<b>Next vehicle inspection</b>	01.12.2024
<b>Service documentation</b>	Nonexistent
<b>Trailer coupling</b>	Fix
<b>Rain sensor</b>	Unavailable
<b>Operating manual</b>	Unavailable
<b>Repainting</b>	Found Plastic parts could not be evaluated by means of paint thickness measurement.
<b>Inspection Condition</b>	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202405-26245

If you have any questions, please state the report number and date

Date: 10.05.2024

**Tires / Rims**

Axis / Size	Tires	Profile [mm]
#1 225/70 R15 front axle	All-season tyre on Steel rim	4/4
#2 225/70 R15 rear axle		7/7

The state of the tyres is roadworthy.

**Brakes**

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

**Value decreasing factors / signs of usage**

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Paint chipping	Slight	
2	Bumper front	Scratch	Slight	
3	Fender ri	Scratch	Slight	
4	Door FR	Scratch	Slight	
5	Door FR	Scratch	Slight	
6	Side panel right	Scratch	Slight	
7	Bumper rear	Scratch	Slight	
8	Tailgate	Scratch	Slight	
9	Side panel left	Scratch	Slight	

REPORTNUMBER: 202405-26245

If you have any questions, please state the report number and date

Date: 10.05.2024

## Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Engine bonnet; ~ 190µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

## Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

## Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 10.05.2024



---

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

**Attached:** 13 overview pictures, 9 damage pictures

REPORTNUMBER: 202405-26245

If you have any questions, please state the report number and date

Date: 10.05.2024

## Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



REPORTNUMBER: 202405-26245

If you have any questions, please state the report number and date

Date: 10.05.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202405-26245

If you have any questions, please state the report number and date

Date: 10.05.2024



Image 13

### Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2



Image 3: siehe pos.3




Image 4: siehe pos.4



REPORTNUMBER: 202405-26245

If you have any questions, please state the report number and date

Date: 10.05.2024




Image 5: siehe pos.5




Image 6: siehe pos.6



Image 7: siehe pos.7




Image 8: siehe pos.8



Image 9: siehe pos.9