



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-26030

If you have any questions, please state the report number and date

Date: 23.04.2024

Report

Subject	Report
Inspection date/location	22.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	HEF KM 125
Vehicle Identification Number	WAUZZZF4XJA036377



REPORTNUMBER: 202404-26030

If you have any questions, please state the report number and date

Date: 23.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	22.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	HEF KM 125
Vehicle type	Estate Car
Manufacturer	Audi
Model / Sales description	A4
Key numbers HSN/TSN	0588 / BIU
Vehicle identification number	WAUZZZF4XJA036377
Previous owners	2
First registration	17.09.2018
Mileage	97.397 km
Colour / Colour Code	BRAUN
Fuel Type	CNG
Cubic Capacity / Power	1.984 cm ³ / 125 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	06.02.2023 / 86.674 km
Next vehicle inspection	30.01.2025
Service documentation	Nonexistent (Von Ölzettel abgelesen)
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202404-26030

If you have any questions, please state the report number and date

Date: 23.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/50 R17 front axle	Winter tyre on Aluminium rim	7/6
#2 225/50 R17 rear axle		6/7

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet		Slight	
2	Fender le	Stone chip	Slight	
3	Windshield	Stone chip	Slight	
4	Door panel FL	Scratch	Slight	
5	Door RL	Dent	Slight	
6	Side panel left		Slight	
7	Door entry RR	Scratch	Medium	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Side panel le.; ~ 180µm
- Side panel ri.; > 1500µm
- Door r.r.; ~ 180µm

REPORTNUMBER: 202404-26030

If you have any questions, please state the report number and date

Date: 23.04.2024

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 23.04.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 8 damage pictures

REPORTNUMBER: 202404-26030

If you have any questions, please state the report number and date

Date: 23.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-26030

If you have any questions, please state the report number and date

Date: 23.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-26030

If you have any questions, please state the report number and date

Date: 23.04.2024



Image 13



Image 14



Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202404-26030

If you have any questions, please state the report number and date

Date: 23.04.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.6



Image 8: Siehe Pos.7