



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202409-27658

If you have any questions, please state the report number and date

Date: 18.09.2024

Report

Subject	Report
Inspection date/location	18.09.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	A-SY 5124
Vehicle Identification Number	ZFA26300006R45463



REPORTNUMBER: 202409-27658

If you have any questions, please state the report number and date

Date: 18.09.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	18.09.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	A-SY 5124
Vehicle type	Van
Manufacturer	Fiat
Model / Sales description	Doblò Cargo 1.6 Multijet 16V SX
Key numbers HSN/TSN	1727 / All
Vehicle identification number	ZFA26300006R45463
Previous owners	1
First registration	23.04.2020
Mileage	118.570 km
Colour / Colour Code	WEISS
Fuel Type	Diesel
Cubic Capacity / Power	1.598 cm ³ / 77 kW
Number of doors / seats	4 / 2
Transmission	Manual gearbox
Number of keys	1
Last maintenance	01.06.2023 / 90.182 km
Next vehicle inspection	01.04.2026
Service documentation	Available
Trailer coupling	No
Rain sensor	Unavailable
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202409-27658

If you have any questions, please state the report number and date

Date: 18.09.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 185/65 R15 front axle	Winter tyre on Steel rim	3/3
#2 185/65 R15 rear axle		3/3

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Bumper rear	Scratch	Slight	
4	Fender le	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202409-27658

If you have any questions, please state the report number and date

Date: 18.09.2024

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 18.09.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 4 damage pictures

REPORTNUMBER: 202409-27658

If you have any questions, please state the report number and date

Date: 18.09.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202409-27658

If you have any questions, please state the report number and date

Date: 18.09.2024



Image 7



Image 8



Image 9



Image 10



Image 11




Image 12

REPORTNUMBER: 202409-27658

If you have any questions, please state the report number and date

Date: 18.09.2024




Image 13



Image 14

MODELL	263	
INSPEKTION		<input checked="" type="checkbox"/>
MOTORÖLWECHSEL		<input checked="" type="checkbox"/>
VORGESEHEN BEI KM...		
DURCHFÜHRT BEI KM...	20182	
FAHRGESTELL-NR.	ZFA26300006R45463	
DATUM	16.23	
MGS Motor Gruppe Service GmbH & Co. KG 92637 Weiden Nikolaus-Otto-Str. 2 Tel. 0961/4671824		
MODELL		

Image 15

Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2

REPORTNUMBER: 202409-27658

If you have any questions, please state the report number and date

Date: 18.09.2024



Image 3: siehe pos.3



Image 4: siehe pos.4