



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024

Report

Subject	Report
Inspection date/location	23.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	HD-NG 1812
Vehicle Identification Number	WDD2054041F491501



REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	23.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	HD-NG 1812
Vehicle type	Cabriolet/Roadster
Manufacturer	Mercedes-Benz
Model / Sales description	C 220 d Cabriolet
Key numbers HSN/TSN	1313 / FHR
Vehicle identification number	WDD2054041F491501
Previous owners	2
First registration	17.11.2016
Mileage	71.058 km
Colour / Colour Code	SCHWARZ
Fuel Type	Diesel
Cubic Capacity / Power	2.143 cm ³ / 125 kW
Number of doors / seats	2 / 4
Transmission	Manual gearbox
Number of keys	2
Last maintenance	Unknown
Next vehicle inspection	01.11.2023
Service documentation	Nonexistent
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/45 R18 front axle	Summer tyre on Aluminium rim	5/5
#2 245/40 R18 rear axle		7/7

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim FR	Scratch	Severe	
2	Aluminium rim RR	Scratch	Severe	
3	Windshield	Stone chip	Slight	
4	Bonnet	Stone chip	Slight	
5	Bumper front	Stone chip	Slight	
6	Mirror cap left	Stone chip	Slight	
7	Door FL	Stone chip	Slight	
8	Door FL	Scratch	Medium	
9	Door FR	Stone chip	Slight	
10	Mirror cap right	Stone chip	Slight	
11	Tire FL		Severe	

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 23.04.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 21 overview pictures, 12 damage pictures

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024



Image 13



Image 14



Image 15



Image 16



Image 17



Image 18

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024



Image 19



Image 20



Image 21

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4




Image 5: Siehe Pos.5



Image 6: Siehe Pos.5



Image 7: Siehe Pos.6



Image 8: Siehe Pos.7

REPORTNUMBER: 202404-26053

If you have any questions, please state the report number and date

Date: 23.04.2024



Image 9: Siehe Pos.8



Image 10: Siehe Pos.9



Image 11: Siehe Pos.10



Image 12: Siehe Pos.11