



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025

Report

Subject	Report
Inspection date/location	31.01.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	CW-S 5847
Vehicle Identification Number	WDB9106211P104081

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	31.01.2025 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	CW-S 5847
Vehicle type	Van
Manufacturer	Mercedes-Benz
Model / Sales description	211 CDI Sprinter Kompakt VA Kasten
Key numbers HSN/TSN	1313 / HRQ
Vehicle identification number	WDB9106211P104081
Previous owners	1
First registration	17.04.2019
Mileage	185.555 km
Colour / Colour Code	
Fuel Type	Diesel
Cubic Capacity / Power	2.143 cm ³ / 84 kW
Number of doors / seats	5 / 3
Transmission	Manual gearbox
Number of keys	2
Last maintenance	22.12.2023 / 157.334 km
Next vehicle inspection	01.02.2026
Service documentation	Available
Trailer coupling	Fix
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/65 R16 front axle	All-season tyre on Steel rim	5/5
#2 225/65 R16 rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Severe	
2	Bonnet	Stone chip	Slight	
3	Bumper front	Scratch	Slight	
4	Fender le	Stone chip	Slight	
5	Door FL	Scratch	Severe	
6	Door panel FL	Scratch	Medium	
7	Side panel left	Scratch	Slight	
8	Tailgate	Scratch	Medium	
9	Bumper rear	Scratch	Slight	
10	Door RR	Dent	Slight	
11	Door FR	Scratch	Severe	
12	Door panel FR	Scratch	Medium	

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 03.02.2025



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 14 overview pictures, 13 damage pictures

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025



Image 13




Image 14

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025



Image 5: Siehe Pos.5



Image 6: Siehe Pos.5



Image 7: Siehe Pos.6



Image 8: Siehe Pos.7



Image 9: Siehe Pos.8



Image 10: Siehe Pos.9

REPORTNUMBER: 202502-29243

If you have any questions, please state the report number and date

Date: 03.02.2025



Image 11: Siehe Pos.10



Image 12: Siehe Pos.11



Image 13: Siehe Pos.12