



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26141

If you have any questions, please state the report number and date

Date: 02.05.2024

Report

Subject	Report
Inspection date/location	02.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	SÖM-AM 30E
Vehicle Identification Number	WS5B16GAAJA800236



REPORTNUMBER: 202405-26141

If you have any questions, please state the report number and date

Date: 02.05.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	02.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	SÖM-AM 30E
Vehicle type	Minivan/Minibus
Manufacturer	Andere
Model / Sales description	Street Scooter 20 Work Box
Key numbers HSN/TSN	1681 / 000
Vehicle identification number	WS5B16GAAJA800236
Previous owners	2
First registration	13.05.2019
Mileage	6.560 km
Colour / Colour Code	
Fuel Type	Electric
Cubic Capacity / Power	/ 38 kW
Number of doors / seats	2 / 2
Transmission	Automatic transmission
Number of keys	2
Last maintenance	Unknown
Next vehicle inspection	01.01.2026
Service documentation	Nonexistent
Trailer coupling	No
Rain sensor	Unavailable
Operating manual	Unavailable
Repainting	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202405-26141

If you have any questions, please state the report number and date

Date: 02.05.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 195/65 R15 front axle	Winter tyre on Steel rim	6/6
#2 195/65 R15 rear axle		7/7

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	Not detectable
Disc	adequate	Drum brakes

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bumper front	Stone chip	Slight	
2	Door FR	Stone chip	Slight	
3	Side panel right	Scratch	Slight	
4	Tailgate	Dent	Slight	
5	Door RL	Scratch	Slight	
6	Door FL	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202405-26141

If you have any questions, please state the report number and date

Date: 02.05.2024

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 02.05.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 9 overview pictures, 6 damage pictures

REPORTNUMBER: 202405-26141

If you have any questions, please state the report number and date

Date: 02.05.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202405-26141

If you have any questions, please state the report number and date

Date: 02.05.2024



Image 7



Image 8



Image 9

Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2

REPORTNUMBER: 202405-26141

If you have any questions, please state the report number and date

Date: 02.05.2024



Image 3: siehe pos.3



Image 4: siehe pos.4



Image 5: siehe pos.5



Image 6: siehe pos.6