



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25858

If you have any questions, please state the report number and date

Date: 10.04.2024

Report

Subject	Report
Inspection date/location	09.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	EN-DK414
Vehicle Identification Number	W1K2130191B088455



REPORTNUMBER: 202404-25858

If you have any questions, please state the report number and date

Date: 10.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	09.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	EN-DK414
Vehicle type	Saloon
Manufacturer	Mercedes-Benz
Model / Sales description	E 300 d 4Matic 9G-TRONIC Avantgarde
Key numbers HSN/TSN	2222 / AEN
Vehicle identification number	W1K2130191B088455
Previous owners	1
First registration	13.06.2022
Mileage	27.283 km
Colour / Colour Code	Graphitgrau Metallic
Fuel Type	Diesel
Cubic Capacity / Power	1.993 cm ³ / 195 kW
Number of doors / seats	4 / 5
Transmission	Automatic transmission
Number of keys	
Last maintenance	19.06.2023 / 25.025 km
Next vehicle inspection	01.06.2025
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202404-25858

If you have any questions, please state the report number and date

Date: 10.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/55 R17 front axle	Summer tyre on Aluminium rim	5/5
#2 225/55 R17 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	adequate
Disc	good	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Slight	
2	Bonnet	Stone chip	Slight	
3	Bumper front	Stone chip	Slight	
4	Door FL	Dent	Slight	
5	Door FR	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202404-25858

If you have any questions, please state the report number and date

Date: 10.04.2024

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 10.04.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 5 damage pictures

REPORTNUMBER: 202404-25858

If you have any questions, please state the report number and date

Date: 10.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-25858

If you have any questions, please state the report number and date

Date: 10.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-25858

If you have any questions, please state the report number and date

Date: 10.04.2024



Image 13



Image 14

Reg. Zulassung	13.06.2022		
VIN	W1K2130191B088455		
Nächster Service	06.2024 50025 km	Nächste HU	06.2025
Bitte beachten Sie die zusätzlichen Informationen in Ihrem Fahrzeug, für Individualität, Servicezeit und Serviceintervalle liegen zur Durchführung der nächsten Servicezeit			
Servicebericht 1		Datum	19.06.2023
Mercedes-Benz	Jägerme GmbH In der Glasleke 33 Schwelm	Rep.-Auftr.-Nr.	AU709962
		Laufleistung	25025 km
geführter Service		Zusatzarbeiten	
Service A		Staubfilter erneuert	<input checked="" type="checkbox"/>
505		AdBlue® aufgefüllt	<input checked="" type="checkbox"/>
-2 Tage		Motor: Öl- und Filterwechsel	<input checked="" type="checkbox"/>
-123 km			
Öl/Viskosität		Bis zum nächsten fälligen Service	
Motor Öl		Mercedes-Benz Mobilio	<input checked="" type="checkbox"/>
229-52		Garantie gegen Durchrostung	<input checked="" type="checkbox"/>
5W-30			
		Service-Intervall nach Vorgaben der Mercedes-Benz AG	

Image 15

Damage pictures



Image 1: Siehe Pos.1




Image 2: Siehe Pos.2

REPORTNUMBER: 202404-25858

If you have any questions, please state the report number and date

Date: 10.04.2024




Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5