



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202408-27444

If you have any questions, please state the report number and date

Date: 30.08.2024

Report

Subject	Report
Inspection date/location	30.08.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	M-ST3451
Vehicle Identification Number	W0VEFYHYCKJ569057



REPORTNUMBER: 202408-27444

If you have any questions, please state the report number and date

Date: 30.08.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	30.08.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	M-ST3451
Vehicle type	Van
Manufacturer	Opel
Model / Sales description	Combo Cargo 1.5 D Edition
Key numbers HSN/TSN	1844 / AIQ
Vehicle identification number	W0VEFYHYCKJ569057
Previous owners	1
First registration	22.05.2019
Mileage	157.356 km
Colour / Colour Code	Jade Weiß
Fuel Type	Diesel
Cubic Capacity / Power	1.499 cm ³ / 75 kW
Number of doors / seats	4 / 2
Transmission	Manual gearbox
Number of keys	2
Last maintenance	30.11.2022 / 125.060 km
Next vehicle inspection	01.07.2025
Service documentation	Available
Trailer coupling	No
Rain sensor	Unavailable
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202408-27444

If you have any questions, please state the report number and date

Date: 30.08.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/60 R16 front axle	Summer tyre on Steel rim with wheel cover	5/5
#2 205/60 R16 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	adequate
Disc	good	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Fender le	Stone chip	Slight	
4	Tailgate	Deformation	Slight	
5	Bumper rear	Scratch	Slight	
6	Door FR	Scratch	Slight	
7	Windshield	Stone chip	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202408-27444

If you have any questions, please state the report number and date

Date: 30.08.2024

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 30.08.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 14 overview pictures, 7 damage pictures

REPORTNUMBER: 202408-27444

If you have any questions, please state the report number and date

Date: 30.08.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202408-27444

If you have any questions, please state the report number and date

Date: 30.08.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202408-27444

If you have any questions, please state the report number and date

Date: 30.08.2024



Image 13




Image 14

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4

REPORTNUMBER: 202408-27444

If you have any questions, please state the report number and date

Date: 30.08.2024



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6




Image 7: Siehe Pos.7