



Gerlach & Schröder GbR  
Nürnberger Str. 34  
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024

## Report

<b>Subject</b>	Report
<b>Inspection date/location</b>	24.04.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Registration number</b>	WES-KG468
<b>Vehicle Identification Number</b>	WF0FXXWPCFMB26803



REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024

## Report

<b>Subject</b>	Report
<b>Client</b>	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
<b>Inspection date/location</b>	24.04.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
<b>Registration number</b>	WES-KG468
<b>Vehicle type</b>	Estate Car
<b>Manufacturer</b>	Ford
<b>Model / Sales description</b>	Mondeo Turnier 2.0 EcoBlue Aut. Titanium
<b>Key numbers HSN/TSN</b>	8566 / BJB
<b>Vehicle identification number</b>	WF0FXXWPCFMB26803
<b>Previous owners</b>	1
<b>First registration</b>	05.07.2021
<b>Mileage</b>	110.546 km
<b>Colour / Colour Code</b>	Magnetic-Grau Metallic
<b>Fuel Type</b>	Diesel
<b>Cubic Capacity / Power</b>	1.997 cm <sup>3</sup> / 110 kW
<b>Number of doors / seats</b>	5 / 5
<b>Transmission</b>	Automatic transmission
<b>Number of keys</b>	2
<b>Last maintenance</b>	12.05.2023 / 91.883 km
<b>Next vehicle inspection</b>	01.07.2024
<b>Service documentation</b>	Available
<b>Trailer coupling</b>	Swiveling
<b>Rain sensor</b>	Available
<b>Operating manual</b>	Unavailable
<b>Repainting</b>	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
<b>Inspection Condition</b>	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024

**Tires / Rims**

Axis / Size	Tires	Profile [mm]
#1 215/55 R17 front axle	Summer tyre on Aluminium rim	6/5
#2 215/55 R17 rear axle		6/5

The state of the tyres is roadworthy.

**Brakes**

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

**Value decreasing factors / signs of usage**

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Scratch	Severe	
3	Bumper front	Stone chip	Slight	
4	Door FL	Scratch	Slight	
5	Door entry FL	Dent	Slight	
6		Burn hole	Severe	
7	Bumper rear	Scratch	Slight	
8	Door RR	Stone chip	Slight	
9	Door FR	Scratch	Slight	
10	Fender ri	Stone chip	Slight	

REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024

## Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

## Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

## Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 24.04.2024



---

Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

**Attached:** 16 overview pictures, 10 damage pictures

REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024

## Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024



Image 13



Image 14



Image 15




Image 16

### Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.7



Image 8: Siehe Pos.8



REPORTNUMBER: 202404-26060

If you have any questions, please state the report number and date

Date: 24.04.2024



**Image 9: Siehe Pos.9**



**Image 10: Siehe Pos.10**