



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25996

If you have any questions, please state the report number and date

Date: 19.04.2024

Report

Subject	Report
Inspection date/location	19.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	
Vehicle Identification Number	VF1RFB00356365261



REPORTNUMBER: 202404-25996

If you have any questions, please state the report number and date

Date: 19.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	19.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	
Vehicle type	Estate Car
Manufacturer	Renault
Model / Sales description	Megane 1.5 DCI 110 FAP ZEN
Key numbers HSN/TSN	/
Vehicle identification number	VF1RFB00356365261
Previous owners	
First registration	02.06.2017
Mileage	103.901 km
Colour / Colour Code	WEISS
Fuel Type	Diesel
Cubic Capacity / Power	1.461 cm ³ /
Number of doors / seats	5 / 5
Transmission	Manual gearbox
Number of keys	1
Last maintenance	30.05.2023 / 88.613 km
Next vehicle inspection	
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202404-25996

If you have any questions, please state the report number and date

Date: 19.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/55 R16 front axle	Winter tyre on Aluminium rim	2/2
#2 205/55 R16 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Door RR	Scratch	Slight	
4	Door entry RR	Scratch	Slight	
5	Bumper rear	Scratch	Slight	
6	Aluminium rim FR	Paint chipping	Medium	
7	Aluminium rim RR	Paint chipping	Medium	
8	Aluminium rim RL	Paint chipping	Medium	
9	Aluminium rim FL	Paint chipping	Medium	

REPORTNUMBER: 202404-25996

If you have any questions, please state the report number and date

Date: 19.04.2024

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 19.04.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 9 damage pictures

REPORTNUMBER: 202404-25996

If you have any questions, please state the report number and date

Date: 19.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-25996

If you have any questions, please state the report number and date

Date: 19.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11




Image 12

REPORTNUMBER: 202404-25996

If you have any questions, please state the report number and date

Date: 19.04.2024



Image 13



Image 14



Image 15




Image 16

Damage pictures



Image 1: siehe pos.1




Image 2: siehe pos.2

REPORTNUMBER: 202404-25996

If you have any questions, please state the report number and date

Date: 19.04.2024



Image 3: siehe pos.3




Image 4: siehe pos.4



Image 5: siehe pos.5



Image 6: siehe pos.6



Image 7: siehe pos.7



Image 8: siehe pos.8



Image 9: siehe pos.9