



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-25909

If you have any questions, please state the report number and date

Date: 12.04.2024

Report

Subject	Report
Inspection date/location	12.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	KO-NE 4417
Vehicle Identification Number	VF1RFB00958573570



REPORTNUMBER: 202404-25909

If you have any questions, please state the report number and date

Date: 12.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	12.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	KO-NE 4417
Vehicle type	Estate Car
Manufacturer	Renault
Model / Sales description	Megane Grandtour ENERGY dCi 110 EDC
Key numbers HSN/TSN	3333 / BFV
Vehicle identification number	VF1RFB00958573570
Previous owners	1
First registration	02.08.2017
Mileage	104.775 km
Colour / Colour Code	Weiss
Fuel Type	Diesel
Cubic Capacity / Power	1.461 cm ³ / 81 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	28.09.2023 / 100.649 km
Next vehicle inspection	01.02.2025
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202404-25909

If you have any questions, please state the report number and date

Date: 12.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/55 R16 front axle	Summer tyre on Aluminium rim	4/4
#2 205/55 R16 rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Mirror cap right	Scratch	Slight	
4	Door entry FR	Scratch	Slight	
5	Door entry RR	Scratch	Slight	
6	Side panel right	Scratch	Slight	
7	Bumper rear	Scratch	Slight	
8	Side panel left	Scratch	Slight	
9	Door entry FL	Scratch	Slight	
10	Mirror cap left	Scratch	Slight	

REPORTNUMBER: 202404-25909

If you have any questions, please state the report number and date

Date: 12.04.2024

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Side panel ri.; ~ 190µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 12.04.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 13 overview pictures, 10 damage pictures

REPORTNUMBER: 202404-25909

If you have any questions, please state the report number and date

Date: 12.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-25909

If you have any questions, please state the report number and date

Date: 12.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-25909

If you have any questions, please state the report number and date

Date: 12.04.2024

Wartung PF A+B X X	Autohaar Adamczyk GmbH & Co. KG Reparatur-Vertragsgewerbe Mannstraße 71-73 39448 Wolfburg Telefon 05363/2141 Fax -3610
Kontrolle auf Korrosion: OK <input checked="" type="checkbox"/> Nicht OK* <input type="checkbox"/> *siehe spezifische Seite	
Datum: 23.04.23 Km-Stand: 100649	Rechnungs-Nr.:
Art der Arbeit: Wartung A+B X Öl, PC, ZR X	Stempel Autohaar Adamczyk GmbH & Co. KG Reparatur-Vertragsgewerbe Mannstraße 71-73 39448 Wolfburg Telefon 05363/2141 Fax -3610
Kontrolle auf Korrosion: OK <input checked="" type="checkbox"/> Nicht OK* <input type="checkbox"/> *siehe spezifische Seite	

Image 13

Damage pictures




Image 1: siehe pos.1



Image 2: siehe pos.2



Image 3: siehe pos.3




Image 4: siehe pos.4

REPORTNUMBER: 202404-25909

If you have any questions, please state the report number and date

Date: 12.04.2024



Image 5: siehe pos.5



Image 6: siehe pos.6



Image 7: siehe pos.7



Image 8: siehe pos.8



Image 9: siehe pos.9




Image 10: siehe pos.10