

Date: 15.04.2024

REPORTNUMBER: 202404-25924

If you have any questions, please state the report number and date

Report

Subject Report

Inspection date/location 15.04.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2,

DE-36179 Bebra

Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra

Registration number

Vehicle Identification Number VSSZZZKLZMR014255

15.04.2024 VIN: VSSZZZKLZMR014255; Report number: 202404-25924 Page 1 of 8



Date: 15.04.2024

REPORTNUMBER: 202404-25924

If you have any questions, please state the report number and date

Report

Subject Report

Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra Inspection date/location 15.04.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2,

DE-36179 Bebra

Registration number

Vehicle typeSaloonManufacturerSeat

Model / Sales description Leon 1.5 TSI ACT OPF

Key numbers HSN/TSN

Vehicle identification number VSSZZZKLZMR014255

Previous owners 1

First registration 15.12.2020
Mileage 95.558 km
Colour / Colour Code Weiss
Fuel Type Petrol

Cubic Capacity / Power 1.498 cm³ / 96 kW

Number of doors / seats 5 / 5

Transmission Manual gearbox

Number of keys 1

Last maintenance Unknown

Next vehicle inspection

Service documentation Nonexistent

Trailer coupling No

Rain sensorAvailableOperating manualAvailableRepaintingNot Found

Plastic parts could not be evaluated by means of paint

thickness measurement.

Inspection Condition non-dismantled, roadworthy, traffic safe

15.04.2024 VIN: VSSZZZKLZMR014255; Report number: 202404-25924 Page 2 of 8

REPORTNUMBER: 202404-25924

If you have any questions, please state the report number and date Date: 15.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/55 R16 front axle	Summer tyre on Aluminium rim	7/7
#2 205/55 R16 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Bumper rear	Scratch	Slight	
4	Tailgate panel	Scratch	Slight	
5	Roof	Dent	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

15.04.2024 VIN: VSSZZZKLZMR014255; Report number: 202404-25924 Page 3 of 8

Date: 15.04.2024

REPORTNUMBER: 202404-25924

If you have any questions, please state the report number and date

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

15me

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 15.04.2024

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 14 overview pictures, 5 damage pictures

15.04.2024 VIN: VSSZZZKLZMR014255; Report number: 202404-25924 Page 4 of 8

Date: 15.04.2024

REPORTNUMBER: 202404-25924

If you have any questions, please state the report number and date

Overview pictures



Image 1



Image 3



Image 5



Image 2



Image 4



Image 6

15.04.2024 VIN: VSSZZZKLZMR014255; Report number: 202404-25924 Page 5 of 8

Date: 15.04.2024

REPORTNUMBER: 202404-25924

If you have any questions, please state the report number and date



Image 7



Image 9



Image 11



Image 8



Image 10



Image 12

15.04.2024 VIN: VSSZZZKLZMR014255; Report number: 202404-25924 Page 6 of 8

Date: 15.04.2024

REPORTNUMBER: 202404-25924

If you have any questions, please state the report number and date







Image 14

Damage pictures



Image 1: siehe pos.1



Image 3: siehe pos.3



Image 2: siehe pos.2



Image 4: siehe pos.4

15.04.2024 VIN: VSSZZZKLZMR014255; Report number: 202404-25924 Page 7 of 8

Date: 15.04.2024

REPORTNUMBER: 202404-25924

If you have any questions, please state the report number and date



Image 5: siehe pos.5

15.04.2024 VIN: VSSZZZKLZMR014255; Report number: 202404-25924 Page 8 of 8