



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202605-33302

If you have any questions, please state the report number and date

Date: 05.05.2026

Report

Subject	Report
Inspection date/location	04.05.2026 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	LB-FM 4756
Vehicle Identification Number	TMAJB81BANJ146272



REPORTNUMBER: 202605-33302

If you have any questions, please state the report number and date

Date: 05.05.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	04.05.2026 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	LB-FM 4756
Vehicle type	SUV/Off-road Vehicle/Pickup Truck
Manufacturer	Hyundai
Model / Sales description	Tucson
Key numbers HSN/TSN	1349 / AFT
Vehicle identification number	TMAJB81BANJ146272
Previous owners	1
First registration	24.02.2022
Mileage	40.874 km
Colour / Colour Code	Grau
Fuel Type	Hybrid/Petrol
Cubic Capacity / Power	1.598 cm ³ / 110 kW
Number of doors / seats	5 / 5
Transmission	Manual gearbox
Number of keys	2
Last maintenance	25.02.2026 / 40.824 km
Next vehicle inspection	01.02.2027
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202605-33302

If you have any questions, please state the report number and date

Date: 05.05.2026

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 235/55 R19 front axle	Summer tyre on Aluminium rim	4/4
#2 235/55 R19 rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Slight	
2	Bonnet	Stone chip	Slight	
3	Seat FL	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

REPORTNUMBER: 202605-33302

If you have any questions, please state the report number and date

Date: 05.05.2026

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 05.05.2026



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 3 damage pictures

REPORTNUMBER: 202605-33302

If you have any questions, please state the report number and date

Date: 05.05.2026

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202605-33302

If you have any questions, please state the report number and date

Date: 05.05.2026



Image 7



Image 8



Image 9



Image 10




Image 11




Image 12

REPORTNUMBER: 202605-33302

If you have any questions, please state the report number and date

Date: 05.05.2026



Image 13



Image 14




Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202605-33302

If you have any questions, please state the report number and date

Date: 05.05.2026



Image 3: Siehe Pos.3