



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202404-26024

If you have any questions, please state the report number and date

Date: 22.04.2024

Report

Subject	Report
Inspection date/location	22.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	UN-SW960
Vehicle Identification Number	ZCFA775B602676761



REPORTNUMBER: 202404-26024

If you have any questions, please state the report number and date

Date: 22.04.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	22.04.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	UN-SW960
Vehicle type	Van
Manufacturer	Iveco
Model / Sales description	IVECO Eu.Car.ML75E16EVI_C
Key numbers HSN/TSN	4192 / 000
Vehicle identification number	ZCFA775B602676761
Previous owners	1
First registration	06.06.2018
Mileage	255.861 km
Colour / Colour Code	
Fuel Type	Diesel
Cubic Capacity / Power	4.485 cm ³ / 118 kW
Number of doors / seats	4 / 3
Transmission	Manual gearbox
Number of keys	1
Last maintenance	Unknown
Next vehicle inspection	01.06.2024
Service documentation	Nonexistent (Kein Servicenachweis vorhanden)
Trailer coupling	No
Rain sensor	Unavailable
Operating manual	Unavailable
Repainting	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202404-26024

If you have any questions, please state the report number and date

Date: 22.04.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/75 R17,5 front axle	Winter tyre on Steel rim	9/9
#2 225/75 R17,5 rear axle		15/15

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	Not detectable
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bumper front	Crack	Slight	
2	Side panel left	Dent	Slight	
3	Tailgate	Paint chipping	Severe	
4	Side panel right	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202404-26024

If you have any questions, please state the report number and date

Date: 22.04.2024

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 22.04.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 19 overview pictures, 4 damage pictures

REPORTNUMBER: 202404-26024

If you have any questions, please state the report number and date

Date: 22.04.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202404-26024

If you have any questions, please state the report number and date

Date: 22.04.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202404-26024

If you have any questions, please state the report number and date

Date: 22.04.2024



Image 13



Image 14



Image 15



Image 16



Image 17



Image 18

REPORTNUMBER: 202404-26024

If you have any questions, please state the report number and date

Date: 22.04.2024



Image 19

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4