



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202402-25124

If you have any questions, please state the report number and date

Date: 12.02.2024

Report

Subject	Report
Inspection date/location	12.02.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	OF-MB 1503
Vehicle Identification Number	KNAE551CDK6057555



REPORTNUMBER: 202402-25124

If you have any questions, please state the report number and date

Date: 12.02.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	12.02.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	OF-MB 1503
Vehicle type	Saloon
Manufacturer	Kia
Model / Sales description	Stin.3.3T-GDI AWD OPF GT 269 A
Key numbers HSN/TSN	8253 / AIA
Vehicle identification number	KNAE551CDK6057555
Previous owners	1
First registration	04.09.2019
Mileage	117.328 km
Colour / Colour Code	
Fuel Type	Petrol
Cubic Capacity / Power	3.342 cm ³ / 269 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	05.06.2023 / 109.866 km
Next vehicle inspection	01.09.2024
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202402-25124

If you have any questions, please state the report number and date

Date: 12.02.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/40 R19 front axle	Summer tyre on Aluminium rim	6/6
#2 225/40 R19 rear axle		7/7

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	near-new	good
Disc	near-new	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim FR	Scratch	Medium	
2	Bonnet	Stone chip	Slight	
3	Roof	Stone chip	Slight	
4	Fender ri	Stone chip	Slight	
5	Mirror cap right	Stone chip	Slight	
6	Door FR	Scratch	Slight	
7	Side panel right	Scratch	Slight	
8	Tailgate panel	Scratch	Slight	
9	Bumper rear	Scratch	Slight	
10	Door FL	Scratch	Slight	
11	Bumper front	Scratch	Slight	

REPORTNUMBER: 202402-25124

If you have any questions, please state the report number and date

Date: 12.02.2024

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 12.02.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 14 overview pictures, 11 damage pictures

REPORTNUMBER: 202402-25124

If you have any questions, please state the report number and date

Date: 12.02.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202402-25124

If you have any questions, please state the report number and date

Date: 12.02.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202402-25124

If you have any questions, please state the report number and date

Date: 12.02.2024



Image 13




Image 14

Damage pictures



Image 1: siehe pos.1




Image 2: siehe pos.2



Image 3: siehe pos.3



Image 4: siehe pos.4

REPORTNUMBER: 202402-25124

If you have any questions, please state the report number and date

Date: 12.02.2024




Image 5: siehe pos.5




Image 6: siehe pos.6



Image 7: siehe pos.7



Image 8: siehe pos.8



Image 9: siehe pos.9



Image 10: siehe pos.10



Image 11: siehe pos.11