



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202601-32408

If you have any questions, please state the report number and date

Date: 20.01.2026

Report

Subject	Report
Inspection date/location	20.01.2026 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	M-S2137E
Vehicle Identification Number	WBATS110509D56399

REPORTNUMBER: 202601-32408

If you have any questions, please state the report number and date

Date: 20.01.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	20.01.2026 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	M-S2137E
Vehicle type	Estate Car
Manufacturer	BMW
Model / Sales description	X3
Key numbers HSN/TSN	0005 / CYB
Vehicle identification number	WBATS110509D56399
Previous owners	2
First registration	25.09.2020
Mileage	50.576 km
Colour / Colour Code	
Fuel Type	Hybrid/Petrol
Cubic Capacity / Power	1.998 cm ³ / 135 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	07.07.2025 / 48.198 km
Next vehicle inspection	30.09.2027
Service documentation	Electronically
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

REPORTNUMBER: 202601-32408

If you have any questions, please state the report number and date

Date: 20.01.2026

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/60 R18 front axle	Summer tyre on Aluminium rim	5/5
#2 225/60 R18 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	good
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Slight	
2	Bonnet	Stone chip	Slight	
3	Bumper front	Stone chip	Slight	
4	Side panel right	Dent	Slight	
5	Door RR	Dent	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

REPORTNUMBER: 202601-32408

If you have any questions, please state the report number and date

Date: 20.01.2026

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.
The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 20.01.2026



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 6 damage pictures

REPORTNUMBER: 202601-32408

If you have any questions, please state the report number and date

Date: 20.01.2026

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202601-32408

If you have any questions, please state the report number and date

Date: 20.01.2026



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202601-32408

If you have any questions, please state the report number and date

Date: 20.01.2026



Image 13



Image 14



Image 15



Image 16

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202601-32408

If you have any questions, please state the report number and date

Date: 20.01.2026



Image 3: Siehe Pos.3



Image 4: Siehe Pos.3



Image 5: Siehe Pos.4



Image 6: Siehe Pos.5