



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024

Report

Subject	Report
Inspection date/location	04.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	BI-XX1110
Vehicle Identification Number	WDD2130341A486586



REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	04.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	BI-XX1110
Vehicle type	Saloon
Manufacturer	Mercedes-Benz
Model / Sales description	E 350d 4M Avantgarde
Key numbers HSN/TSN	1313 / HBB
Vehicle identification number	WDD2130341A486586
Previous owners	1
First registration	26.06.2018
Mileage	124.600 km
Colour / Colour Code	blau
Fuel Type	Diesel
Cubic Capacity / Power	2.987 cm ³ / 190 kW
Number of doors / seats	4 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	19.06.2023 / 115.453 km
Next vehicle inspection	30.06.2025
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 245/40 R19 front axle	Summer tyre on Aluminium rim	1/1
#2 275/35 R19 rear axle		4/3

The state of the tyres is not roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	good
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet		Medium	
2	Windshield	Stone chip	Slight	
3	Door panel FL	Scratch	Slight	
4	Door RL	Scratch	Slight	
5	Door panel RR		Slight	
6	Tailgate		Medium	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Bumper fr.;
- Bumper re.;
- Fender ri.; ~ 180µm
- Door f.r.; ~ 150µm

REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 04.05.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 20 overview pictures, 6 damage pictures

REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 13



Image 14



Image 15



Image 16



Image 17



Image 18

REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 19



Image 20

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4

REPORTNUMBER: 202405-26182

If you have any questions, please state the report number and date

Date: 04.05.2024



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6