



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024

Report

Subject	Report
Inspection date/location	02.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	K-LU 1988 E
Vehicle Identification Number	WDD2130161A719853

REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	02.05.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	K-LU 1988 E
Vehicle type	Saloon
Manufacturer	Mercedes-Benz
Model / Sales description	E 300d AMG Line Aut.
Key numbers HSN/TSN	1313 / HSL
Vehicle identification number	WDD2130161A719853
Previous owners	2
First registration	27.08.2019
Mileage	92.855 km
Colour / Colour Code	SCHWARZ
Fuel Type	Hybrid/Diesel
Cubic Capacity / Power	1.950 cm ³ / 143 kW
Number of doors / seats	4 / 4
Transmission	Automatic transmission
Number of keys	2
Last maintenance	17.08.2023 / 85.279 km
Next vehicle inspection	01.08.2024
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found
	Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 245/45 R18 front axle	Winter tyre on Aluminium rim	8/8
#2 275/40 R18 rear axle		8/8

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim FL	Scratch	Slight	
2	Aluminium rim RL	Scratch	Slight	
3	Bonnet	Stone chip	Slight	
4	Bumper front		Slight	
5	Windshield	Stone chip	Slight	
6	Door FL	Scratch	Slight	
7	Door entry FL	Scratch	Slight	
8	Door entry RL	Scratch	Slight	
9	Bumper rear	Scratch	Medium	
10	Side panel right	Scratch	Slight	
11	Door entry RR	Scratch	Slight	
12	Door panel RR	Scratch	Slight	

REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024

13	Door FR	Dent	Slight
14	Door panel FR	Deformation	Slight

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 02.05.2024



Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 13 damage pictures

REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024



Image 13



Image 14



Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6



Image 7: Siehe Pos.8



Image 8: Siehe Pos.9

REPORTNUMBER: 202405-26156

If you have any questions, please state the report number and date

Date: 02.05.2024



Image 9: Siehe Pos.10



Image 10: Siehe Pos.11



Image 11: Siehe Pos.12



Image 12: Siehe Pos.13



Image 13: Siehe Pos.14