

Date: 27.04.2023

REPORTNUMBER: 202304-22140

If you have any questions, please state the report number and date

Report

Subject Report

Inspection date/location 26.04.2023 | Dick Automobile e.K., Ernst-Abbe-Str. 2,

DE-36179 Bebra

Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra

Registration number M-TR 2563

Vehicle Identification Number WBA6V51070EM37663

27.04.2023 VIN: WBA6V51070EM37663; Report number: 202304-22140 Page 1 of 8



Date: 27.04.2023

REPORTNUMBER: 202304-22140

If you have any questions, please state the report number and date

Report

Subject Report

Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra 1nspection date/location 26.04.2023 | Dick Automobile e.K., Ernst-Abbe-Str. 2,

DE-36179 Bebra

Registration numberM-TR 2563Vehicle typeEstate CarManufacturerBMW

Model / Sales description 220i Gran T.Sp.141 Aut.5d

Key numbers HSN/TSN 0005 / CKF

Vehicle identification number WBA6V51070EM37663

Previous owners 1

First registration 17.08.2018
Mileage 109.852 km

Colour / Colour Code Fuel TypeBLAU

Petrol

Cubic Capacity / Power 1.998 cm³ / 141 kW

Number of doors / seats 5 / 5

Transmission Automatic transmission

Number of keys 1

Last maintenance 19.07.2022 / 96.136 km

Next vehicle inspection01.05.2024Service documentationElectronicallyTrailer couplingDetachableRain sensorAvailableOperating manualAvailableRepaintingNot Found

Plastic parts could not be evaluated by means of paint

thickness measurement.

Inspection Condition non-dismantled, roadworthy, traffic safe

27.04.2023 VIN: WBA6V51070EM37663; Report number: 202304-22140 Page 2 of 8

REPORTNUMBER: 202304-22140

If you have any questions, please state the report number and date Date: 27.04.2023

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 205/55 R17 front axle	Summer tyre on Aluminium rim	4/4
#2 205/55 R17 rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	near-new	good
Disc	near-new	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Slight	
2	Bonnet	Stone chip	Slight	
3	Bumper front	Stone chip	Slight	
4	A-pillar left	Stone chip	Slight	
5	Side panel left	Dent	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

27.04.2023 VIN: WBA6V51070EM37663; Report number: 202304-22140 Page 3 of 8

Date: 27.04.2023

REPORTNUMBER: 202304-22140

If you have any questions, please state the report number and date

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 27.04.2023

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 18 overview pictures, 6 damage pictures

27.04.2023 VIN: WBA6V51070EM37663; Report number: 202304-22140 Page 4 of 8

Date: 27.04.2023

REPORTNUMBER: 202304-22140

If you have any questions, please state the report number and date

Overview pictures



Image 1



Image 3



Image 5



Image 2



Image 4



Image 6

27.04.2023 VIN: WBA6V51070EM37663; Report number: 202304-22140 Page 5 of 8

Date: 27.04.2023

REPORTNUMBER: 202304-22140

If you have any questions, please state the report number and date



Image 7



Image 9



Image 11



Image 8



Image 10



Image 12

27.04.2023 VIN: WBA6V51070EM37663; Report number: 202304-22140 Page 6 of 8

Date: 27.04.2023

REPORTNUMBER: 202304-22140

If you have any questions, please state the report number and date



Image 13



Image 15



Image 17



Image 14



Image 16



Image 18

27.04.2023 VIN: WBA6V51070EM37663; Report number: 202304-22140 Page 7 of 8

Date: 27.04.2023

REPORTNUMBER: 202304-22140

If you have any questions, please state the report number and date

Damage pictures




Image 1: Siehe Pos.1



Image 3: Siehe Pos.3



Image 5: Siehe Pos.4



Image 2: Siehe Pos.2



Image 4: Siehe Pos.3



Image 6: Siehe Pos.5